LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For comers in

ror comers in			1	
Iron	Located In:	Corner Code #		
(County)	•			
1. Public Land Survey	T R T R T R T R T R			
2. Property Controlling in Section	S 23 T 42N R 31W S 23 T 42N R 31W S T R	J8 12		
3. Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Nur	mber
4. Lot No. , Re 5. Private Claims	ecorded Plat J8 10/	/14/2009	A B C D E F G H I o	J K L M
above were in conformance with instructions of the United States a Court of Law and /or that the	in a field survey on 12 10/ 74, Michigan P.A. of 1970, the corner regulations and rules therefore as requi Department of the Interior, Bureau of I corner points mentioned in lines 3, 4 an	do hereby state points mentioned in lines 1 and ired in the current manual of surveilland Management or by a decree of 5 above were in conformance with	ey 5 of 6 -18 -17 -16 -15 -1 th 7	1112-
the rules of the Michigan Boar re-established, monumented, reco	ord of Land Surveyors or by a Decree evvered, found as expressed below:	e of a Court of Law; established	d, 8 19 20 21 22 9 10 30 29 28 27 2	24-25-
NOTE: Not more than 2 core on this certificate.	ners, all in the same town and range	e, may be recorded	11 12 31 32 33 34 3	35 36

A. Description of original monument and accessories and/or subsequent restoration:

(J8) Center of Section 23. 1990 - K.L.Sackett RLS established the corner at the intersection of 1/4 lines. Set 1"IDx32" I.pipe with 4" aluminum cap. 7" Sugar S81E 19.2', 4" Sugar N28E 13.6', 4" Ironwood N52W 3.8', sq'd 12" Aspen South 2.0'.

(12-Sec. 23) South 1/16 corner, Section 23. 1990 - K.L.Sackett RLS established the corner midway and on a straight line between Quarter corner south and Center of Section north. Set 1"IDx32" I.pipe with 4" alum. cap in west side of Camp 5 Road ditch. 16" Hemlock S70W 16.6', 3" Sugar N13W 10.0', 7" Maple S78E 42.6', Sq'd 4" Yellow Birch N47W 3.5'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(J8) Found the 1990 monument in good condition and at record bearing and distance from two remaining 1990 BTS. Accepted the monument as a careful and faithful establishment of the position of the corner.

(12-Sec. 23) Found the 1990 monument in good condition, midway and on line between Quarter corner south and Center of Section north. The Maple BT SE was found at record bearing and distance. The Hemlock BT SW, at record bearing. Accepted the monument as a careful and faithful establishment of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(J8) Fd. 1"ID I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 5" Sugar N30E 13.5' old blazes 1990 BT 13" Sq'd Aspen S12W 2.15' do mrkd "C1/4 BT" 6" Sugar S37E 11.95' 9" Sugar N40W 22.45' do Bearings are magnetic.

(12) Fd. 1"ID I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: Maple S77E 43.1' scribing visible 1990 BT 18" Hemlock S72W 27.25' do do 5" Y.Birch N67W 23.85' mrkd "1/16S BT" do 6" Y.Birch N15W 25.35' Steel sign post N61W 1.1' Bearings are magnetic.

Signed by Styph I Sunt	led.	Date	11/03/2009
Surveyor's Michigan License No.	33986		
For the Michigan Departm	ent of Natural Resources	, Office of Land and	l Facilities

FORM APPROVED BY MICHIGAN STATE BOARD

(AND Sevile sed Jan., 1983

STEPHAN J YSZKOSKI LAND SURVEYOR

16346 16345