## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

(County)	_ Located In:	Corner Code #	5	
1. Public Land Survey	TR _	33W K3		
2. Property Controlling in Section	S T R S 12 T 43N R S T R	33W SMC S. of L3		
3. Miscellaneous Property in Sec.	S T R			
4. Lot No. , Rec	corded Plat		Register of Deeds Stamp & File N	
5. Tilvace Claims	⊕ K3	08/11/2011		J K L M
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey 5				
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7				
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:			stablished, 8 19 20 21 23	23 24
NOTE: Not more than 2 corn on this certificate.	ers, all in the same town ar	nd range, may be recorded	10 30 29 28 27 11 12 31 32 33 4	-26 -25
A. Description of original m	Onument and accessories	and/or subsequent restoration		35 36

(K3) Corner common to Sections 1-2-11-12. 1983 - Remonumented by Glenn C. Van Neste PS 27464 at the location of a found very old squared Cedar post and painted lines. Set 5/8"x18" rebar with RLS cap. 8" Maple N36E 25.53', 5" dbl. Y.Birch S26E 33.19', 16" Maple S55W 2.88', 13" Basswood N54W 28.60'. This corner has been used subsequently by several local land surveyors for extensive further surveys in and around Sections 1 and 11.

(SMC S. of L3) Special Meander corner on the bank of the Paint River at its intersection with the N-S 1/4 line of Section 12, being on the line between Government Lots 2 and 3. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(K3) Found a 5/8" dia. rebar in good condition and at record bearing and distance from the 1983 witnesses: The Y.Birch 6" S23E 33.35' to a meas. nail with tag "GFA 27464", with upper blaze, now standing dead; Maple S55W 2.88' a cut stump; Basswood 14" N53W 28.5' to a meas. nail with tag "GFA 27464", with old blaze, in good condition. Accepted the rebar as the best available evidence of the position of the original corner.

(SMC S. of L3) Established the corner on a straight line between Quarter corners L3 and L5 about 12' north of the apparent OHWM of the Paint River, being 2063.71' south of Quarter corner L3.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(K3) Found 5/8" dia. rebar Fd. meas. nail with GFA tag 27464 in: 6" Y.Birch S23E 33.35' old blaze, dead 14" Basswood N53W 28.5' old blaze Set meas. nail with MDNR tag in the side of: 8" Sugar N87E 13.8' mrkd "S1 NBT" 5" Sugar S88W 31.5' "S11 NBT" 11" Sugar S40E 17.95' "S12 NBT" Set sq'd Cedar post adjacent. Bearings are magnetic.

(SMC) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 8" Ash N58E 23.3' mrkd "SMC BT" 8" Ash S68W 25.4' do

9" Ash N55W 7.0' do 14" Maple NO4W 43.3' do Set sq'd Cedar post adjacent. Bearings are magnetic.

Signed by Date 09/21/2011 Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Management Division

16730 16726 FORM APPROVED BY MICHIGAN STATE BOARD

SAND SO 14, 1975 Rervised Oct., 1995

STEPHAN J

SZYSZKOSK

LAND

SURVEYOR