

SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Iron
(County)

Located in:

Corner Code #

1. Public Land Survey

T 44N R 37W

✓ A.B-1 (ool)

T 45N R 37W

A.B-13 (ool)

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

00 DEC -8 PM 1:05

L.C. Records: L. 8, P. 267

Gibson & Sons
REGISTERED LAND SURVEYORS

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

East Meander Corner to Section 31, T45N, R37W

East Meander Corner to Section 6, T44N, R37W

I, Gary L. Pisoni, in a field survey on October 18, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established on June 9, 1847 by John Burt, U.S. Deputy Surveyor.

Original Corner: Cedar Meander Post

Original Bearing Trees:

Tamarack	14"	N 65° E	13 links (8.58 feet)
Hemlock	5"	S 20° E	25 links (16.50 feet)

In 1970, Donald D. Lappala RLS USFS, restored the corner position with a 5"x5" concrete monument with iron bar in center being 10' from waters edge and 6" above ground surface and marking the NW corner of the Assessor's Plat of Tamarack Lake.

In 1982, John H. Fisher RLS found the above described monument and established the following new bearing trees:

Cherry	5"	N 16° E	16.40 feet
NW corner of cabin foundation		S 13° E	102.80 feet
Steel sign post		N 75° E	1.75 feet

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original B.T.s found.

Found monument as described above and the following corner references:

Black Cherry	10"	N 24° E	16.31 feet
Steel sign post		N 77° E	1.8 feet

Monument is 6" above ground surface and 10' from waters edge.

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Established the following new bearing trees: (All measurements taken to a nail in side of tree) No scribing or B.T. signs

White Birch(clump)	13"	S 75° E	28.73 feet
Red Maple	15"	S 08° W	45.50 feet

00-035

Signed by Gary L. Pisoni Date 11-13-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

