LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #						
1. Public Land Survey	T 45N R 31W	M7 (GCDB 700400)						
2. Property Controlling in Section3. Miscellaneous Property in Sec.	T 45N R 31W S T R S T R S T R S T R S T R S T R	M8 (GCDB 700340)						
4. Lot No. , Rec 5. Private Claims	corded Plat		Register of Deeds Stamp & File Number A B C D E F G H I J K I I					
above were in conformance with re- instructions of the United States D a Court of Law and /or that the co	74, Michigan P.A. of 1970, the corner p egulations and rules therefore as required epartment of the Interior, Bureau of Lar orner points mentioned in lines 3, 4 and 1 of Land Surveyors or by a Decree	d in the current manual of survey nd Management or by a decree of 5 above were in conformance with	y 5					
NOTE: Not more than 2 corner on this certificate.	ers, all in the same town and range,	may be recorded	10 30 29 26 27 26 25 11 12 31 32 33 34 35 36					
A. Description of original monument and accessories and/or subsequent restoration:								

(M7) Corner common to Sections 13-24 T45N-R31W and 18-19 T45N-R30W. 1969 - Reestablished by A.O. Enger RLS at a position which corresponds with the original field note calls to ridge tops east, west, north and south. Set 1"IDx36" I.pipe with 4" aluminum cap. R.Maple 8" S61°E 23 links, Balsam 9" N4 1/2°E 26 links, W.Birch 9" S68°W 22 links.

(M8) Quarter corner common to Sections 24 T45N-R31W and 19 T45N-R30W. 1969 - Reestablished by A.O. Enger RLS 40.00 chains north of M9 and on line between M9 and M7. Set 1"IDx36" I.pipe with 4" aluminum cap. B.Spruce 4" S5 1/2°W 8.5 links, B.Spruce 5" N57°W 31 links, Balm of Gilead 12" N41°E 14.5 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(M7) Found the 1969 monument in good condition, no evidence of the 1969 witnesses. Verified the position of the monument by coordinating with monumented M8, M9, K7 and L7, and found it to be in accord with Mr. Enger's record with the exception of distance M7-M8, which was found to be 2412.60' (Enger=38.66 chains=2551.56'). The difference with the 1969 record appears to be the result of a measuring error by Mr. Enger made between M8 and the south shore of Little Sundog Lake, the error clearly evident in the 1969 measurement to the lakeshore when compared to aerial photography. I accepted the position of the monument as a careful and faithful reestablishment of the position of the original corner.

(M8) Found the 1969 monument in good condition, in accord with the 1969 record position, and at record bearing and distance from the 1969 witnesses, now all rotted stumps. Accepted the monument as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5" Sugar N32°E 19.9' mrkd "S18 NBT" 12" Maple S59°E 15.55' "S19 NBT" 7" Sugar S80°W 2.7' "S24 NBT" 3" Sugar N42°W 13.3' "S13 NBT" Set sq'd cedar post adjacent.	Conservation cap. Set measuring nail tag in the side of:	with MDNR "1/4S NBT" do do do
---	--	-------------------------------

Bearings are magnetic.	Coordinates are	MCS83	in meters,	NAD83 (2011)	Epoch	2010.00	datum
Coord. Ref.=	NGS PID RL0202:	N= 150	6159.364 m.	E= 7917031	370 m		

Signed by Date 04/25/2016

Surveyor's Michigan License No.

33986 For the Michigan Department of Natural Resources, Forest Resources Division

SURVEYOR FORM APPROVED BY MICHIGAN STATE BOARD DI

TEPHAN

LAND

SZKOS