SURVEY & REMONUMENTATION

JUL 2 3 1997

For corners in

COMMISSION

LIBER 2PAGE 103

	CORNER RECORDATION CERTIFICA Requirement of Act 74, Mich. P.A. 19		_
	,	No g	ŕ
le:	Correct Code #		2

Kalamazoo Located In: orner Code # (County) Richland Twp. 1. Public Land Survey R 10W C11 R R 2. Property Controlling R in Section R 3. Miscellaneous R Property in Sec.

RECEIVED FOR RECORD BOUNTY OF KALAMAZ

Register of Deeds Stamp & File Number

4. Lot No,	Recorded Plat	
5. Private Claims		
-		-

, in a field survey on May 7 , 19 <u>96</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the comer points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

i A	В	C D	E F	G H	I J H	к ь м
2 —	- 6 —	 	44	3	2	
3	+		-			
4	-7-	 	 	-10	11	12-
5						
6	-1 <mark>8</mark>	1,7	16	15	14	 1 _. 3
7	 		 	 		
8 -	_1 9	20_	21	22	23	24—
9 —				<u> </u>		
10—	_3 _. 0	29_	28	27	26	25
11	-					
12	 -31	32_	-33 33	34	35	—36—
İ	ŀ	1 1		1 1		Ĭ

- A. Description of original monument and accessories and/or subsequent restoration:
- 1827 Southwest corner established by U.S. Deputy Surveyor John Mullet Accessories: 7" W. Oak South 11 degrees West 27 Links 14" W. Oak North 65 degrees East 24 Links
- 1887 F. Hodgman: Found old stake hole in center of road and in line with fence north, set post. 10" Hickory South 55 degrees West 66 Links 6" Hickory North 56 degrees West 76 Links.

1982 Al McMachen, L.C.R.C. L.1, P. 843: iron rod.
Date? KCRC witness notes: Tile 1' West of fence North N. Road fence North 23.5' 2½ " axel iron over tile, tile 1.8' below ground. Fence East 25.2', fence post South 45 degrees West 36.8'

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Origainal monument and accessories not recovered.

Found 1/2" rebar in mon. box. Dug below to find axle iron surrounded by 3"-8" stones directly beneath 1/2" rebar. Continued digging to find clay tile 1.5'+/- below road surface and 0.63' North and 0.35' West of 1/2" rebar and axle iron.

> RATIFIED BY KALAMAZOO COUNT REMONUMENTATION PEER GROUP 6-20-1996

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C11, Southwest Corner Section 29, Town 1 South, Range 10 West, ratified by Kalamazoo County Remonumentation Peer Group on June 20, 1996. The position of the clay tile is accepted as a careful and faithful perpetuation of the position of the original corner. Removed rebar and axle iron and set a 20" Harrison Monument over the tile in mon. box.

Fnd. nail in 24" Oak South 45 degrees East 49.02' Fnd. nail in 8" Oak North 16 degrees West 22.04" Fnd. nail in 16" Oak North 64 degrees West 48.16" Set P.K. nail in 7" Walnut South 1 degree West 30.08"

Signed by Surveyor's Michigan License No 38116

Date 12/28/96

