JAN 25 2001

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, Mich. P.A. 1970

SECTION

Fo L <u>a</u> l	r corners in ke		Loca	ited in:		Corner Coo	e#		1	LAK	ERO		PAGE	#21	¥3
1.	Public Land Survey		T_17 N T			R 11 W	E-4			lay				-	
						R				skolik.	e Cén	(7	Region	لومان EDS	
			<u>ַ</u>	Γ		R				REGI	STE	ROF	DEE	DS	
			Ţ	<u> </u>		R									
2.		s	T -		_R		778/027								
	in Section	s	<u> </u>		_B	·		Registe	er of D	Deeds	Stan	որ & F	File Nı	ımber	
3.	****	s			_R			, region		-		.p			
4.	Property in Sec. Lot NoRecord	S ded Plat	<u> </u>		R				ав (съя	EFG	3 H]	IJĸ	LM	
5.	Private Claims							1 2	6	5	4	3	2	1	
hei	<u>Robert L. Wetherell,</u> in a reby certify that under re	quiremen	ts of	P.A. 74,	, Mio	higan P.A. o	2000, do f 1970, the corner	3 4 5	7	8	9	10	11	12	
rul	points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by decree of a Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were								18	17	16	15	14	13	
Co									19	20	21	22	23	24	
In conformance with the rules of the Michigan Board of Land Surveyors or by a Decree Of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:								9 10 11	30	29	28	27	26	25	
rec	xoverea, iouna as expres	ssea Delo	w:					12	31	32	33	34	35	36	

A. Description of original monument and accessories and/or subsequent restoration:

1838 - J. Hodgson, G.L.O.

#1 - 7" Beech N49°E 44 Links

#2 - 16" Beech N45°W 8 Links

E-4 - 1/4 Corner common to Sections 8 & 9, T17N, R11W

1978 - C. Cole, LS 17615

Set rebar on line between Section corners and in line with fence to East.

' RECORDED

#3 - 18" Ash S87°E 116.45'

#4 - 5" Tw. Apple N12°E 151.18'

#5 - 12" Apple S4°E 178.22'

#6 - Measured 2641.16' North to Sec. Corner

#7 - Measured 2631.63' South to Sec. Corner

B. Description of corner evidence found and/or method applied in restoring of reestablishing corner:

I found Cole's 1/2" Capped rebar in line with fences East and West and in the centerline of North and South road, (there is approximately 12 feet of road fill in this area).

Condition of the accessories are as follows: #1 Gone, #2 Gone, #3 Found in poor condition, #4 Found in good condition, #5 Found in poor condition, #6 Measured 2641.07', #7 Measured 2631.61'.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I replaced the ½" rebar with a ¾" x 24" rebar with Lake County Remon Cap, and is accepted as a careful and faithful rcestablishment of the position of the original corner.

10" R. Pine N31°E 104.81' (60d spike in S.E. side) 14" Tw. Elm S82°E 23.77' (60d spike in N. side)

12" Tw. Elm S18°W 126.50' (60d spike in W. side)

5" Elm N13°W 90.42' (60d spike in W. side)

8" Apple N12°E 151.14' (nail in W. side) #4

PATIFIED BY THE LAND CO. PEER REVIEW GROUP IN ACCORDANCE WITH P.A. 345 CHAIRMAN R. S.W. DATE 4-11-2000

ST BIENTE ** ** ROBERTI VETHEREI ÁND. SURVEYOR 24624 19 (4 8 9 9

Surveyor's Michigan License No. 24624

Date April 12, 2000