JAN 2 2 2001

Filed under Remonumentation Act 345 of 1990

SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Lenawee (County)									LIBEI	1 1	PAGI		
		Located	f In:	Corner Code #	B1 42	,4 ,					TE OF N ENRUEE FILI	COUNT'	
1. P	ubļic Land Survey	T T	R <u>· 3 - E</u> R R	<u>C-2</u>	-					28 JUN VICTI REG	2000 ORIA J ISTER	. DANI	EL
ir 3. N	roperty Controlling n Section Miscellaneous troperty in Sec	ST ST ST	_ R _ R		Re	-	er of D						-
4 1	ot No:	Recorded Plat				1 2	6 d	5	4	3 H	2	1	1
5. P	rivate Claims					3 4	7	- 8	9	-10	11	12	
I, Glenn E, Richardin a field survey onApril18,2000_, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5							1;8	17	·· 16·	15 -	14	13-	
							19	20	21	22	23	24	
above Court	were in conformance	with the rules of th	e Michigan Board	d of Land Surveyors or by a te- e-monumented, recovered,	Decree of a	9 10 11	30	29	28	27	26	25	
		•	ne same town a	and range, may be record	ied	12 13	31	32	33	34	35	3,6	
Α.	Description of original	inal monument ar	nd accessories	and/or subsequent resto	ration:								
	1943 Walter F 1960 Kenneth engineer and M the east 1/4 co 1986 I found a checked ± loca	razier survey ca Suydam while e Ar. Frazier gave rner of Section 6 3 <u>/4"</u> iron pipe in tion of the 1960	lled for "large or mployed by Whim the field now. The notes or swamp with or survey.	est in swamp Poplar 6 to end post - W 1/4 post Selater Frazier did the fie otes and he did the coreall for "Old corner post coupling on the top & pieupling on the top and respondence or the top and respondence	Sec. 5" lid work on mputations lieces of tile	a su and	urvey wrote emain	for Front the constant of the	ed Old descrip old wo	otions	that b	egin a	il at
В.	Description of corr	ner evidence foun	d and/or metho	od applied in restoring or	reestablish	ing c	corner:						

April 18, 2000 I found the 3/4" iron pipe which checked the one remaining witness. Replaced the found iron pipe with a 30" Harrison Monument. I found a stone on the west side of the remains of a Cedar post 1' under the water. Had to remove the stone to set the Harrison Monument. I placed stones and pieces of tile around the monument to hold it in place as the muck was saturated with water. I found a 3/4" galv. pipe in fence row 368.07' east. (No occupation north) W.E.F. 1943 survey record=364.98.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

30" Harrison Monument and is accepted as the best available evidence of the position of the original corner.

Fd. dbl hd nail & disc in 8" Box Elder S 20° W 12.70 Dbl hd nail & disc in 12" Box Elder West 25.40 Dbl. hd nail & disc in 10" Box Elder S 45° E 16.47 Carsonite post North 0.38 Steel fence post South 0.8 Centerline of Elliott Drain North 30'±



	4.4	Ì
Ratified by Peer Group in accordance with P.A. 345	Co. Rep Stenn & Richard Date May 9, 2000	
Signed by Alenne Richard Date	June 5, 2000	
Glenn E. Richard	FORM ARRIGINATION STATE BOARD I	