

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Luce	Located In:	Corner Code #
(County)		
1. Public Land Survey	T 46N R 10W	C3
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6	5		4		3		2		1		
3													
4		7	8		9		10		11		12		
5													
6		18	17		16		15		14		13		
7													
8		19	20		21		22		23		24		
9													
10		30	29		28		27		26		25		
11													
12		31	32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 05/20/2010 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(C3) Corner common to Sections 5-6-7-8. 1853 - Established by Geo.H.Cannon Deputy Surveyor in a correctional survey. Monumented by a wood post. Maple 7" S68E 29 links, Y.Birch 10" S19W 18 links. 1974 - Remonumented by Billy D. Buckler RLS at the position of a found scribed post, "probably set by H.Lawrence, RLS with remains of Maple stump in proper position". Set 1" pipe with 4" aluminum cap. 6" W.Pine S55W 23.9', 8" B.Spruce N11W 21.2'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(C3) No definite evidence of the original BT Maple SE was found (presumably this is the 'Maple' referred to by Mr. Buckler). Found the 1974 monument in good condition and at record bearing and distance from the 1974 witnesses. The W.Pine SW is in good condition, the B.Spruce NW is a rotted stump. Accepted the monument as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(C3) Found 1"ID I.pipe with 4" MI Dept of Conservation cap.
Set measuring nail with MDNR tag in the side of:
16" W.Pine S61W 24.35' mrkd "S7" 1974 NBT
10" B.Spruce N18W 7.35' mrkd "S6 NBT"
8" B.Spruce N77E 4.65' "S5 NBT"
10" B.Spruce S03E 17.5' "S8 NBT"
Bearings are magnetic.



Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 10/26/2010

For the Michigan Department of Natural Resources and Environment, Forest Management Division