

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Luce	Located In:	Corner Code #
(County)		
1. Public Land Survey	T 49N R 11W	E5
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5					●								
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 07/09/2008 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Corner common to Sections 8-9-16-17. 1854 - Record of Geo. H. Cannon, Deputy Surveyor, states: Post...corner of Sections 8-9-16-17. W.Pine 16" S62W 27 links, W.Pine 11" N41 1/2E 40 links. 1958 - Corner recovered and recorded as follows by Billy D. Buckler, RLS: "Found 2" iron pipe buried in intersection of N-S-E-W firelines. This corner was re-witnessed as set by Marcus Schaaf, Reg. Surveyor. Found two Pine stump bottoms bearing N41E, 40 links and S60W 27 links". New witnesses: 10" Red Pine S20W 55.5 links, 10" Red Pine S32E 44 links. Found no other record of the Schaaf survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found the 2" iron pipe of record, in good condition, buried in the intersection of firelanes N-S-E-W, and at record bearing and distance from the remaining 1958 NBT Red Pine [found as a double Red Pine 14" DBH] to the SE. The Red Pine NBT SW appears to have been removed by earthmoving equipment. The original BTs were not recovered. Accepted the pipe as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found 2" ID iron pipe. Set measuring nail with MDNR tag in the side of:
 14" twin R.Pine S27E 29.55' mrkd "S16" 1958 NBT
 8" W.Pine N53E 27.8' mrkd "S9 NBT"
 11" R.Pine N42W 26.3' "S8 NBT"
 12" W.Pine S58W 31.75' "S17 NBT"
 Bearings are magnetic.



Signed by Stephan J. Szyszkoski Date 02/17/2009
 Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Office of Land and Facilities

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971