LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

			1			
Luce	Located In:	Corner Code #				
(County)	_		3			
1. Public Land Survey	T 50N R 08W	C9 (GCDB 200300)				
2. Property Controlling in Section	S 20 T 50N R 08W S T R	15 (GCDB 220300)	·			
3. Miscellaneous Property in Sec.	S T R S T R S T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R T R R R T R		Position of Donale Change & Fill N.			
	corded Plat		Register of Deeds Stamp & File Number			
5. Private Claims			A B C D E F G H I J K L M			
ı, <u>Stephan J. Szyszkoski</u> , i		9/15/14 do hereby state	3			
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2						
above were in conformance with regulations and rules therefore as required in the current manual of survey 5 instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6 18 17 16 15 14 13						
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7						
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, 8 19 20 21 22 23 24 re-established, monumented, recovered, found as expressed below:						
re-established, monumented, recov	rered, found as expressed below:		9			
NOTE: Not more than 2 corron this certificate.	ners, all in the same town and rang	e, may be recorded	10 30 29 28 27 26 25			
A. Description of original n	nonument and accessories and/or	subsequent restoration:	12 31 32 33 34 35 36			

(C9) Corner common to Sections 19-20-29-30. 1952 - Monumented in the original postion and subsequently recorded in 1953 by Dean C. DeLaMater RLS. "One original B.T. still in place, down, fair condition". Set 1" pipe with 4" brass cap. 10" J.Pine S20°E 10 links. Found no sbusequent record.

(15-Sec. 20) West 1/16 corner between Sections 20 and 29. Not previously monumented.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (C9) The 1952 monument was not recovered and has likely been removed by heavy equipment as it falls just 3' east of an old logging road. Found the 1952 NBT J. Pine dead but in good condition with measuring notch visible. Found the point of the squared post which would have been set adjacent to the monument. Remonumented the corner at record bearing (corrected for declination change by indexing 1952 rec. bearings against observed bearings at corner D9) and distance from the J.Pine NBT, which position is also S16°E 0.5' from the recovered post point. The original B.T. noted in the 1952 record (being a Y.Pine 16" N56E 17 links) is now a stump mound at record bearing and distance.

(15-Sec. 20) Established the position for the corner midway and on the Section line between Quarter corner 1317.65' east and Section corner 1317.65' west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

6" J.Pine S01°W 29.22' "S30 NBT" 9" Oak S63°W 17.62' E= 8126593.437 N= 215327.940 9" W.Pine N04°E 23.15' E= 8126994.926 N= 215336.454		10" Oak S66°E 2.72' 9" W.Pine S02°E 16.23' 9" Oak S63°W 17.62' 9" W.Pine N04°E 23.15'	tag in the side of: mrkd "W1/16 BT" do do do
---	--	---	--

Bearings are magnetic. Coordinates are MCS83 in Coord. Ref.=NGS PID RJ1161: N= 21771	meters, NAD 8.382 m. E=	83(2011) Epoch 201 8133488.614 m.	.0.00 datum.
Signed by Stephen Saysylvoli'	Date	04/29/2015	* STEPHAN J.
Surveyor's Michigan License No. 33986 For the Michigan Department of Natural Resources,	Forest Resources	Division	SZYSZKOSKI LAND SURVEYOR
	FORM API	PROVED BY MICHIGAN STATE BOAR	o in Professions Biggerons 188. 38, 19

AND SUR