

Forestry - Lansing.

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF—	LOCATED IN—	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY.....	42 S. R. 12	1-3
2. PROPERTY CONTROL ING IN SECTION.....	N. S. R.	1
3. MISCELLANEOUS PROPERTY IN SECTION.....	N. S. R.	1
4. LOT NO.	RECORDED PLAT	
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Billy D. Buckler, R. L. S. do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on 8-29-1973 1973, established, re-established, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 1973, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:
Section Corner 2,3,10,11; was set by G. C. Carleton, D. S. on August, 6, 1849.
Bearings were:
Sugar 9° N. 49° W, 21 lks and Sugar 9° S. 19° E, 16 lks.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
Found a 1 1/2" Iron Pipe, which has been used by landowners and T. L. Jackson, R. L. S. in recent years. This location does not agree with railroad survey maps dating back to June, 6, 1839. These maps indicate the corner to be located 93.5' west and 43.2' south of present location, but could find no evidence at that point. I did find remains of concrete footings, lying south of the railroad, which are on the Sec. line, according to the old Survey.

The position of the present corner, in relation to corners found in all four directions would indicate, the true corner should be further north and east, thereby proving the old railroad Survey to be inaccurate.

Since most Surveys appear to begin at this present location, we are accepting this as the Section Corner location in our subsequent Survey.
(See sketch on reverse side.)

C. Re-witnessed corner as marked by 1 1/2" Iron Pipe.

Corner lies on East edge of a road; 18.0' East of Pole line to North and 10.0' South of a Pole line to East.

Witnesses:

Power Pole, N. 40° W, 23.7' and 10" Cedar, S. 75° W, 122.1'

SIGNED BY:

Billy D. Buckler
Billy D. Buckler, R. L. S.

DATE

SURVEYOR'S MICHIGAN REGISTRATION NO. 27.

FOR STATE AND UNITED STATES AGENCIES

SIGNED BY:

DATE

APPROVED AND SIGNED BY:

DATE

SURVEYOR'S MICHIGAN REGISTRATION NO. 27.

Form No. ML 738
BOUNDARY SURV. & CO., SAGINAW, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 20, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS