## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74. Mich. P.A. 1970

Fo	or corners in	•	,						
Mackinac		Located In:	Corner Code ##						
	(County)								
1.	Public Land Survey	T _42N_ R _12N_							
		T R							
		Ţ R							
_	Durantu Cantallina	T R	3	•					
2.	Property Controlling in Section	S35_ T42N_ R _12N S T R	<del>-3</del>						
3	Miscellaneous	S T R		Danistas of	Daada	C4		Mumbe	
٥.	Property in Sec.	S T R		Register of	Deeas	Stam	parile	Numbe	<b>3</b> F
4.	Lot No , F	Recorded Plat		АВ	C D	E F	G H	ΙJΚ	LM
5.	Private Claims					$\top$	TI	ΤI	
				3 6	5- 1	一 i	3-	1 2 -	
						77	11		
Oct 07 1999					−† å	- - 9-	<del> </del>   10-	<del> -</del> 11-	12-1
	I, <u>Stephan J, Szyszkoski</u> , in a field survey on, 19, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned						11		
in	lines 1 and 2 above were i	the The	17	16	-15-	14-	13		
	current manual of survey instructions of the United States Department of the Interior, Bureau of Land					++	++	++	+
	Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5					-21	22-	2'3	<del> </del>
	above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as					++	++	+-+	$\vdash$
	expressed below:					-28	27_	26	25-
NO	NOTE: Not more than 4 corners, all in the same town and range, may be recorded					++	+	$\bot \bot$	$\sqcup \sqcup$
	on this certificate.					33	34_	35	36

- A. Description of original monument and accessories and/or subsequent restoration:
- (II2) Quarter corner common to Sections 34-35. Reestablished in 1964 by Billy D. Buckler RLS midway and on line between Section Corners. 1" pipe with 4" aluminum cap. 9" H. Maple S25W 13 links, 7" H. Maple N27W 12 links. (3-Sec. 35) North 1/16 corner between Sections 34-35. Established in 1964 by Billy D. Buckler RLS midway between 1/4 corner to south and section corner to north, and on line. 1" pipe with 4" brass cap. 15" W.Pine S56E, 16 links (per 11/23/64 correction to 10/20/64 land corner record).
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (II2) Recovered the 1964 monument as described, a 1" ID iron pipe capped with a 4" cast aluminum tablet, appropriately stamped, in good condition, and at record bearing and distance from the 1964 witnesses, both recovered in good condition. Left the monument in place and marked two new witnesses as described below.

(3-Sec. 35) Recovered the monument as described, a 1" ID iron pipe capped with a 4" dia. brass tablet, appropriately stamped, in good condition, and at record bearing and distance from the 1964 witness, also in good condition. Left the monument in place and marked three new trees as described below.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(I12) Found 1" pipe with 4" aluminum cap. Blazed, scribed, and set measuring nails in the following: 14" Maple N21E 7.95' "1/4S NBT 12" Beech N86E 4.35' ďΩ The 1964 witnesses: 16" Maple S26W 9.4' "1/45" 9" Maple N30W 8.25' ďο Bearings are magnetic. Distances are to nail with tag, placed this date.

Surveyor's Michigan License No

(3) Found 1" pipe with 4" aluminum cap. Blazed, scribed, and set measuring nails in the following: 6" Tamarack \$18E 15.9" "N1/16 NBT'

Tamarack S70W 19.4' dο 10" Tamarack N50W 23.5" ďΩ the 1964 witness:

squared and scribed post adjacent.

20" W. Pine S54E 11.2' Bearings are magnetic. Distances are to nail with tag, placed this date. Placed

SZYSZKOSKI

LAND

SURVEYOR

33984 MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 NO. \_\_\_\_\_\_\_\_FORM APPROVED BY MICHIGAN S' For the Michigan Department of Natural Resources - Forest Management Division

REVISED MAY 14, 1975 ...