

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Mackinac Co.

2 Corners.

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. <u>43</u> N. <u>6</u> E. <u>W.</u>	<u>I-2</u> <u>G-10</u>
2. PROPERTY CONTROLL- ING IN SECTION_____	T. _____ N. _____ E. _____ S. _____ R. _____ W. _____	
3. MISCELLANEOUS PROPERTY IN SECTION_____	T. _____ N. _____ E. _____ S. _____ R. _____ W. _____	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Billy D. Buckler, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 12-7, 19 78, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:
Corners set by H. Brevoort Jr., D.S. in 1845.

I-2 Quarter Corner bet. Sec's. 2-3, bearings were: A 10" Spruce marked for Quarter Section Post.

G-10 Quarter Corner bet. Sec's. 27-28, bearings were: Spruce 8, N13°E, 09 lks. and
Spruce 8, N70°W, 07 lks.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

I-2 Corner restored on line and by proportionate measure between two Section Corners.
Corner lies on South side of a low ridge.

G-10 Corner restored midway and on line between two Section Corners. No evidence of original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed 1" pipe with 4" aluminium cap at both corners.

I-2 New Bearings: 7" Cedar, S65°E, 6.3' and 8" Cedar, S73°W, 3.6' and
9" Cedar, N50°E, 7.5'.

G-10 New Bearings: 6" Cedar, N78°E, 23.3' and 6" Cedar, S28°E, 18.25' and
6" Cedar, N38°W, 8.3'.

SIGNED BY

Billy D. Buckler
Billy D. Buckler

DATE 2-23-79

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY

DATE

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY

DATE

MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____