DEC 23 1000

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

	corners in ISTEE (County)	Located In:	Corner Code #		MAN	IISTE	R'S C E CC	UNT	Ÿ	a.n
1. F	oublic Land Survey	T 21N R 16W T R T R	D-13		Xt.	borc	367 1719 142 ROFE	ix		
i 3. I	Property Controlling S n Section S Miscellaneous S T Property in Sec. S	Regist	egister of Deeds Stamp & File Number							
4. l	_ot No, Rec	orded Plat			ав (C D	E F G	- H I	J K	L M
5. I	Private Claims	· · · · · · · · · · · · · · · · · · ·			6	5	4	3	. 2	· 1 ·
			7	3	7	۰	ç	10	17	12
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in tines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land						8 17	-16	15	14	13
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as					19	20	21	22	23	24
•	ressed below:	anner all in the same to	num and range, may be recor	9 10	- 30	29	28	27	26	25
NO A.	on this certificate	•	own and range, may be recorns and/or subsequent restoration	12	31	32	33	34	35	36
	SOUTH QUARTER CORNEL 1838: G.L.O. Survey 11" Y. Pine N-67°-1 7" B. Oak N-30 ½ 1939: M.H. Stickney Iron Pipe No Witne 6" Post 4.5' High(3 1982: Robert Griffi 10" Oak N-42°-W 5" Oak N-10°-E	c OF SECTION 32, T21N-R by John Brink Set pos 31 Lks(1) 7-W 11 Lks(2) Book A, Page 72 sses 1 1 Survey Set Rebar 63.43'(4)	R16W 10° Oak N-42° 10° Oak N-10° 10° Oak N-57°	nackelford L.6 -W 63.43'(4) -E 53.58'(5) -E 60.07'(6) 1.64'(7)	C.R.C S	90-178				
В.	SOUTH QUARTER CORNE APRIL 1998: Found C 11 7 6" 10 5	R OF SECTION 32, T21N-F apped 1/2" Iron Rod #13 "Y. Pine N-67°-E 3 "B. Oak N-30 ½'-W 4.5' "Oak N-42°-W 63 "Oak N-10°-E 53 "Oak N-57°-E 60 st West 1	nod applied in restoring or rees R16W 3584. Condition of the with 31 Lks(1)GONE 11 Lks(2)GONE High (3)GONE 8.43' (4)FOUND Dock Spike 8.58' (5)FOUND Dock Spike 0.07' (6)FOUND Dock Spike 1.64' (7)FOUND Nail 8.70' (8)FOUND			ews:				
C.	SOUTH QUARTER CORNE APRIL 1998: Accepte of the position of 14" 6" 7" 12"	R OF SECTION 32, T21N-I d 1/2" Iron Rod and rep the Corner. Oak N-42°- Trip. Black Oak S-31° White Oak N-10°- Black Oak N-57°- Red Pine S-46°	Diaced with a MANISTER COU. -W 63.46'(4) Dock Spike -E 35.36' 50 Dock Spike -E 60.16'(6) Dock Spike -W 31.88' 60 Penny Na:	nty Monument	as the ratified b adopted Survey a	best by the M pursu and Re	availa	e Count	y Peer 145 of	Group - 1990,
_	ned by	land Hays e No	PICH Date PICH Date * SURVEYOR	July FORM APPROVED	Åv e	AN STATE		LAND SURV	EYORS, JA REVISED MA REVISED	N. 28, 1971 LY 14, 1975 JAN., 1983