## REMON. COR. G-11, HOPE TWP. LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Midland (County)	Located in: Comer Code #	509
Property Controlling in Section     Miscellaneous Property in Sec.	T 16N R 1E	STATE OF HICHIGAN HIDLAND COUNTY REMONUMENTATION & FILED 12/28/2000 8:44:27 AM Register of Deeds Stand & Fre Municer REGISTER OF DEEDS
lines 1 and 2 above were in conformance in the current manual of survey instruct interior, Bureau of Land Management or corner points mentioned in lines 3, 4 and of the Michigan Board of Land Surveyors monumented, re-monumented, recovered	on May 30, 2000, do hereby certify yan P.A. of 1970, the corner points mentioned on with regulations and rules therefore as required ons of the United States Department of the by a decree of a Court of Law and/or that the 15 above were in conformance with the rules or by a Decree of a Court of Law, re-established, it, found as expressed below:	A B C D E F G H I J  2 - 6 - 5 - 4 - 3 - 2 - 3  4 - 7 - 8 - 9 - 10 - 11  5 - 18 - 17 - 16 - 15 - 14  7 - 8 - 19 - 20 - 21 - 22 - 23  9 - 30 - 29 - 28 - 27 - 26  11 - 31 - 32 - 33 - 34 - 35  13

3 1 12 10 9 13 15 14 16 24 22 23 21 26 25 27 28 36 35 34

K L

- A. Description of original monument and accessories and/or subsequent restoration:
- Corner common to Sections 27, 28, 33 and 34 G-11

4

Survey by Glo, 1830's, set post Survey by Gio, 1650 s, see post Survey by F. Gibbs, 1907, 1908, 1917, found cast iron old corner Survey by M. Hunter, 1960, 1967, found 1" square iron Survey by J. Schafer, 1972, 3" pipe on top of 1" bar Survey by R. Strejc, 1976, found Survey by J. Jones, 1980, 1985, found 3/4" pipe in monument box

RICATO RODHEY D. CLAYPOOL LAND MOYEVRASE 

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- Corner common to Sections 27, 28, 33 and 34

Found 1/2" rod in monument box per surveys by F. Gibbs, M. Hunter, J. Schafer, R. Strejc and J.Jones.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- Corner common to Sections 27, 28, 33 and 34

Replaced rod with 3/" pipe and brass cap stamped Midland Co. Remon Cor PS 29241 in monument box and is accepted as the bes available evidence of the position of the original corner.

S 2 Deg E, 28.98, nail and plastic disc in top of post S 20 Deg W, 35.05, pk nail in 4"x4" telephone pole stub N 40 deg W, 57.66, pk nail in power pole. Rec. 57.7, 58.3

N 30 Deg E, 52.2, centerline 12 CMP

Signed by Rodnus D C Surveyor's Michigan License No. 29241

Date 12-12-00

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971 Revised May 14, 1971 Revised Jan., 1983

APPROVED LAND CORNER P.A. 345 OF 1990 **NADLAND COUNTY** 

12/27/00 98