Land Corner Recordation Certificate

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Craig W. McVean							Surve	y Date:	<u>June</u>	<u> 20, 201</u>	<u>7</u>		
For corner(s) in	: Midla	Midland			County	73		·					
Original Public	Land S	urvey (Corner		Corner Code								
S 28	& 33	Ť	16N R	01W	F11								
S		T	R			A	В	C D I	E F (з н	IJł	KLN	۷Į
S	907	Т	R			_ 1 __ _	1	1 2		1 19	- 3		٦1
S		T	R			2	-6	5	4	3	2	11	2
						3			!	-1-	- 1	I	3
Property Controlling Corner					Corner Code	4	7	8	9	- 10 -	- 41	- 12	- 4
S		T	R			- 5	-1			- i	-1-	l	5
S		Τ_	R			- 6	18	17	16	15	14	13	1
S		T	R			0	10	17	16	15	14	- 13	6
S		T	R			7							7
Decrease Common					Corner Code	8	19	20	21	22	23	24	8
Property Corner					Corner Code	9	+		1	1	1	1	9
S		T	R	-		_ 10	30	29	28	27	26	25	10
S		T	R			_11			ò	1			11
S		T	R			- 12	31	- 32 -	33	- 34	35	36	12
S			R				31	10.		34	33	30	
Protracted Public Land Survey Corner					Corner Code	13 A	В	C D	E F	G H	1 J I	KLI	√ 13
S		Τ	R	}									
s		Т	R			_							
S		т	R			_							
s		т _	R	R		_							

Part A: Corner History

 $\underline{\textbf{F11}}$ – ½ corner common to sections 28 & 33, T16N, R1W

1832 – H. Parke – Set qr. sec. post 1) Hemlock 10" N70"W 2 ½ L. 2) Hemlock 10: S81"E 9 ½ L.

- -1852 A. Burt GLO Dependent Resurvey Old qr. corner. Set Post
 3) Hemlock 6" S8"W 23 L.
 4) Hemlock 10" N25"E 14 L.

Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

F11 – ½ corner common to sections 28 & 33, T16N, R1W – No GLO evidence found. Set stamped 4" DNR aluminum cap on 1"x 36" long galvanized iron pipe at record GLO distance west of corner 'G11' based on the following retracement; From corner 'G11' – original corner position – Grid bearing and distance of S89*58'21"W 642.05' [West 9.74 (642.84') W. Pine 12" diameter – GLO] to set 2" aluminum cap on 5/8"x 34" rebar in CL. remain 12" WPS; Extending line west hit east side of stream-6'+/- wide – course south at 2144' [32.45 Ch. (2142') stream 10 L. south – GLO]; thence at S89*58'21"W 2663.74' (2663.76'-ground distance) [West 40.36 Ch. (2663.76') – GLO] from 'G11' to set DNR monument. Felt this was the best fit to the stream crossing and line tree. Corner falls in low area that would be common for Hemlock. No Hemlock present today. Also found ½" capped iron #39074 that is N25°32'E 48.15' from DNR monument. Contacted T. Bebee for information on the capped iron but none was provided. This ½" CIR is basically at a proportional position and on line between his irons ½ mile E & W. Did not accept Mr. Bebee's irons at 'E11' or 'G11' so could not accept this iron either. DNR monument accepted as a careful and faithful reestablishment of the position of the original corner.

Part C: Field Evidence of Perpetuation or Monumentation of Corner

F11 -1/4 corner common to sections 28 & 33, T16N, R1W

4" DNR Aluminum Cap on 1" x 36" long galvanized iron pipe. Set Blue Composite Post 1' North. S29°E 29.03' to set N & T in SE side 3" Oak S07°W 4.90' to set N & T in W side 5" Oak N40°W 12.91' to set N & T in NW side 4" Oak N51°E 20.27' to set N & T in NE side 4" Oak N25°32'E 48.15' to Fd. ½" CIR #39074



Craig W. McVean

Date

2017

Professional Surveyor's License No.:

39088

Prepared By: Craig W. McVean Michigan Dept. of Natural Resources 8015 Mackinaw Trail Cadillac, Michigan 49601