

LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--	MARQUETTE COUNTY LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. <u>48</u> N. <u>X.</u> R. <u>28</u> W.	<u>B-7</u>
2. PROPERTY CONTROLL- ING IN SECTION_____	, T. _____ N. _____ S. _____ R. _____ E. _____ W. _____	
3. MISCELLANEOUS PROPERTY IN SECTION_____	, T. _____ N. _____ S. _____ R. _____ E. _____ W. _____	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		
		REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Arthur O. Enger, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on November 17, 1978, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

1/4 corner between Sections 18 & 19, T48N, R28W
Wood post (Not found. Found 1" O.D. iron pipe driven in place.)
Spruce 8 N65E 5 (Not found. Balsam 9 S27W 36.4 ft., scribed, dead.)
Y. Birch 12 S50W 18 (Probably found. Balsam 15 N32W 18.3 ft., scribed, dead.)

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Re-witnessed corner as found monumented with the iron pipe. Pipe placed by unknown persons, apparently many years ago, and witnessed by the two balsams indicated in A, now dead stumps, but with scribing visible. Found a Y. Birch stump, badly rotted, S51°W 11.8 ft. from pipe, which presumably was an original BT.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1" O.D. iron pipe of unknown length, with top mushroomed from driving.
Cedar 10 N46°W (mag.) 50.6 ft. "1/4S, NBT"
Cedar 8 N62°E (mag.) 57.2 ft. "1/4S, NBT"

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY Arthur O. Enger DATE March 1979

CHIEF OF SURVEY PARTY

MICHIGAN REGISTERED LAND SURVEYOR

Arthur O. Enger

Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

