

SURVEY & REMONUMENTATION

JUN 23 1994

COMMISSION

For corners in
MENOMINEE

(County)

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 Of

P.A. Of 1990 On 5/12, 199 4

Chairman

PAGE # 74 BK. 4
BARBARA MORRISON
REGISTER OF DEEDS
MENOMINEE, WI 49858

RECEIVED FOR RECORD

94 MAY 20 PM 3:32

Register of Deeds Stamp & File Number

	Located In:	Corner Code #
1. Public Land Survey	T 32N R 27W	F-13
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

	A	B	C	D	E	F	G	H	I	J	K	L
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

I, William Lenca, in a field survey on Nov. 15, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1847 - Original Survey by James H. Mullett - B.T.'s - Cedar, 10", N60°W, 48 lks; W. Pine, 20", N27°E, 50 lks. All original evidence for this corner has been destroyed by County Road improvements.
- 1886 - Plat of Survey by Orson Burlingame, Surveyor, shows a section subdivision of Section 33, T32N-R27W. The corner monument is not described and no witnesses are given.
- 1972 - Certified Survey No. 9 recorded by George B. Wilson, RLS No. 17607, indicates that this corner was established on the extension south of a very old fenceline. The survey shows a concrete monument 33 feet north of the corner position. No corner monument is shown at the corner position. The record measurements in this survey along the South Line of the SW 1/4 of Section 33 compare very closely to Burlingame's measurement.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found a P.K. Nail 33 feet south of an existing 4 inch diameter concrete monument on the extension south of a very old fence. Burlingame's measurement west from this corner is 2656. The present measurement west from this corner to an existing concrete monument at the position of the SW corner of Section 33 is 2654.3. This position is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" x 24" Iron Rod/3-1/4" diameter Aluminum cap - stamped for corner in Monument Box:

Concrete Monument	N05°E	33.00 feet
5/8" x 24" Iron Rod/2" Alum. cap marked Witness Marker	N41°E	57.94 feet
5/8" x 24" Iron Rod/2" Alum. cap marked Witness Marker	S10°E	82.11 feet
5/8" x 24" Iron Rod/2" Alum. cap marked Witness Marker	S50°W	53.33 feet
Metal Survey Sign Post	North	33.5 feet

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca Date April 27, 1994
Surveyor's Michigan License No. 26461