

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

for corners in

MENOMINEE
(County)

Located In:

Corner Code: 11

33N 27W

1-2

Public Land Survey

T R

T R

T R

T R

Property Controlling
in Section

S T R

S T R

Miscellaneous

S T R

Property in Sec.

S T R

Lot No. Recorded Plat

Private Claims

William Lenca

Mar 09

95

in a field survey on 19
I hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

Description of original monument and accessories and/or subsequent restoration:
1848: Original Survey by James H. Mullett - B.T.'s - Cedar, 4", S20°E, 05 lks. Tamarack, 14", S42°W, 09 lks. All original
evidence has been destroyed by Highway construction.

1984: Certified Survey No. 381 by George B. Wilson, RLS No. 17607, shows this corner in relation to other corners in Section 3,
T33N-R27W. No corner description or B.T.'s are given. G. B. Wilson's proportioned position along the East line of Section
3 is not correct and was not considered.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

In our 1995 Remonumentation Survey we were unable to find any evidence of this corner. It appears from the map legend in
Certified Survey No. 381 that no corner was set and this position was only computed. As stated in part "A" above, Wilson's
proportion is incorrect based on GLO record measurements. We established this corner position at the correct single proportional
position between the NW Corner and SW Corner of Section 2, T33N-R27W. The corner position thus established is accepted as a
careful and faithful reestablishment of the position of the original corner.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 2" dia. Aluminum Pipe/3-1/4" dia. Alum. cap stamped for corner location:

5/8" x 24" Iron Rod/2" Alum. cap marked "WITNESS MARKER"	S12°E	43.56 feet
5/8" x 24" Iron Rod/2" Alum. cap marked "WITNESS MARKER"	S45°W	46.87 feet
P.K. Nail in Power Pole No. 391	N62°W	72.04 feet
Survey Sign Post	North	0.5 feet



NOTE: All bearings are magnetic bearings. All distances are measured with EDM. Distances to trees are to nail in side of tree.

igned by William Lenca Date Oct. 20, 1995

urveyor's Michigan License No. 26461