{ : ;

Approved by Menomines County
Land Survey Remonumentation
Peer Group Under Act 345 Of
P.A. Of 1990 On 10/26 199

•			11,	EL ANII RES
•	LAND CORNER RECO	RDATION GERTIF	ICATE	Chairman
	Filing Requirement of	Act 74, Mich. P.A	. 1970	87.0 97.0 97.0 97.1
or corners in		1	. B	HEOTHUD FOR 15 110V - 8 ARROSINS (SA
	caled In: Corn	er Code :#/ .	: T	
(County)			1	
	33N 27W T R	I-3		# <u>#</u> \$\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
				性人に見
			· .	☆ 20 三 三
			d	11 11 11 11 11 11 11 11 11 11 11 11 11
			<u> </u>	<sup>(S</sup> 유 ) ~ ㅋ
				<del>-</del> 9
			Register of Deed	s Stamp & File Number
rioperty in oco.				
. Lot No , Recorded Pla	1		— АВС	DEFGHIJKLM
Private Claims			1 i l	
. Theate Glands			2 - 6	5 - 4 - 3 - 1 - 2 - 1 - 1
			3	<del>                                     </del>
	Mar '09 '	. 0	5 · 4	\$ <del>-   -   -   -   -   -   -   -   -   - </del>
William Lenca	trivey on	, 19 ,		<del>_                                    </del>
a haraby certify that under requirements of	P.A. 74, Michigan P.A. of 1970, the	comerpoints mention	ed 6 18	716151413
. times 1 and 2 above were in conformance	e with regulations and rules the	retore as required in	ine[ 1	
are at manual of supply instructions of the	United States Department of the	e interior, Bureau oi La	ing 11	
'anagement or by a decree of a Court of Law pove were in conformance with the rules of	and/or that the corner points me	ntioned in lines 5, 4 air	05 8 19-12	0
ourt of Law; established, re-established	monumented, re-monumente	d, recovered, found	as 9	
xpressed below:			10 -30-2	92625
OTE: Not more than 4 corners, all in	the same town and range.	may be recorded	11	<del>┊</del> <del>┋</del>
on this certificate.	, the come to the end of	•	12 31 3	2 33 34 35 36
. Description of original monument a	nd accessories and/or SUBS	equent restoration:	13	
1848: Original Survey by James evidence has been destroy	H. Mulictt - B.T.'s - Ccdar, 10 yed by Highway construction.	5", N25 <sup>0</sup> E, 13 lks. C	cdar, 10", N80°W, 1	lks. All original
			•	
1977: L.C.R.C. No. 167 by Georgusing 1877 railroad ties. G	ge B. Wilson, RLS No. 17607, B. Wilson's tics- Centerline	, states that a 2" Alu U.S. Hwy. "41", We	m. Pipe/Magnets top st, 96 feet.	and bottom was re-set
. Description of corner evidence fou	nd and/or method applied in	restoring or reestab	olishing corner:	
In our 1995 Remonumentation Surmarked "100 YEAR FLOOD MEN in the centerline of an East - West as the best available evidence of the	OMINEE RIVER". This Cor County Road. This corner pos	ner is located 96 icel sition has been used	East of the centering	OI U.D. IHBIIMAY TI AM
				LAND E
		•	•	# STEASTOR #
				Ho. 26401
				TOTAL CHAIN SURFACE
Description of monument for corne	r and accessories established	d to perpetuate loc	ating the position of	the corner:
Accepted existing 2" dia. Alum. Pi	ne/3-1/4" dia. cap marked "10	0 YEAR FLOOD M	ENOMINEE RIVER	" in Mon. Box.
Accepted existing a did, Admit, 11	tang at 1 month of the water and was	- <b>f</b> -		
5/8" x 24" Iron Rod/2" dia. Alu	m can marked "Witness Mar	ker" South	28.66 fcct	
P.K. Nail in Power Pole	in out marron in incomination	S320W	39.34 feet	
P.K. Nail in Power Pole Chisel mark in North End of M	etal Culvert	N36°W		
	CM CMYOIL	South	29.1 feet	
Metal Survey Sign Post		50001	4	
NOTE: All bearings are magnetic tree.	bearings. All distances are m	casured with a steel	tape. Distances to tre	ees are to nail in side of
<del></del>				
1. 1 1/2 /		-	Oct. 26, 1995	
gned by William	Julle-	Date		
:rveyor's Michigan License No.	26461			ATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
rveyor's imichigan License No			FURM APPROVED BY MICHIGAN 2:	REVISED MAY 14, 1975 REVISED JAN., 1983