## SUHVEY & REMONUMENTATION

FEB 1 1 1998

Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 Of
P.A. Of 1990 On 1992

SECTION	LAND CORNER RECORDATION CERTIFIC Filing Requirement of Act 74, Mich. P.A. 1	CATE Chairmen
For corners in MENOMINEE	Located In: Corner Code #	97 DEC 2
(County)	734N p. 27W M-12	6 2 C
1. Public Land Survey	T34N R 27W T R A 12 T R A 12 T R A 12	2 - M. H.: 2 2 - M. H.: 2 3 D. Y. S. 1 D. T. S. 1
2. Property Controlling in Section	S TR S TR	8 29 F
Miscellaneous     Property in Sec.	S TR	Register of Deeds Stamp & File Number
4. Lot No, Record	ed Plat	ABCDEFGHIJKIM
5. Private Claims		
(SAME AS CORNER A-12	(134N-R20W)	2 6 5 4 3 2 3
William Lenca	in a field survey on 19 <sup>97</sup> do hereby state that under	
requirements of P.A. 74 Michigan	P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in	n - 1
Hustand Chales Department of the Int	ules therefore as required in the current manual of survey instructions of the terior, Bureau of Land Management or by a decree of a Court of Law and to	f 6 18 17 10 15 15 14 15 15
that the assessment montoped it	n lines 3, 4 and 5 above were in conformance with the rules of the Michigan a Decree of a Court of Law, established, re-established, monumented	n _F
recovered, found as expressed bek	W.	8 -19 -20 -21 -22 -23 -24 -
NOTE: Not more than 2 come	ers, all in the same town and range, may be recorded	9
on this certificate.	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	10 30 29 28 27 26 25
		11
		12 31 32 33 35 36 3
		13
A. Description of original monument and accessories and/or subsequent restoration:  1847: Original Survey by H. Floyd - B.T.'s - Tamarack, 9" - S33°W - 40 lks.; Tamarack, 10" - N62°W - 43 lks. All original		
evidence for this of the control of	corner has been destroyed by county road improvements.  No. 215 by William Lenca, RLS No. 26461, states in the legen was set.  No. William Lenca states "Set corner in centerline of County I	d that a 3/4" x 18" Iron Pipe with an  Road North and South and established
S49 <sup>0</sup> E - 42.00'; W	Section corners." - Set 3/4" x 18" Iron Pipe - TIES: Tamaraci V. Birch, 6" - N39°W - 48.70'.	
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:		
using existing B.T.'s as inc	et at this location has been destroyed due to recent county road dicated in Land Corner Recordation Certificate number 292 (so the County Road and midway between the NE Corner and the cal surveyors for many years, and is accepted as the best available.	SE Corner of Section 36, T34N-R27W. This
		OF MICHIGA
		WELIAM * LENCA * LAND
C. Description of monument f	or corner and accessories established to perpetuate locating the	position of the corner + SURVEYOR *
Set 5/8" x 24" Iron Rod/3-	1/4" dia. Alum. cap stamped for corner location in Monument	Box!
10"dia, Tamarack	N49 <sup>o</sup> E : 48.05 feet Scr. NBT	FOED LAND STRONG
9" dia. Tamarack	S64°E   54.48 feet   Scr. NBT S28°W   77.94 feet   Scr. NBT	The state of the s
6" dia. Cedar 7" dia. Cedar	N44°W 49.48 feet Scr. NBT	
Metal Survey Sign Pos	****	
NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.		
Signed by William	y Joseph Date	Dec. 12, 1997

Surveyor's Michigan License No.\_