

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____ T. <u>35</u> N. S., R. <u>29</u> E. W.		L-5
2. PROPERTY CONTROLLING IN SECTION _____ T. _____ N. S., R. _____ E. W.		
3. MISCELLANEOUS PROPERTY IN SECTION _____ T. _____ N. S., R. _____ E. W.		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, David B. Babbitt, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 12/13/82, 19____, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

L-5 S 1/4 Corner of Sec. 12; wood post - Y. Pine 18" - N56°W - 68 lks., Y. Pine 14" - S24°E - 7 lks.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Set from badly burned 20" Y. Pine stump for the N.W. O.B.T. and a definite depression which, when excavated was found to contain charred wood as would be left when a stump burned out. While the Y. Pine stump is too badly burned to show any blazes to identify it as the N.W. O.B.T. and the depression can only be identified as a stump hole, they do fit each other well for bearings and distances recorded for the O.B.T.s and the distance from this position Easterly along the Sec. line to a small stream-recorded as "24.25 stream 4 links, course South" is the same as the G.L.O. recorded distance and crosses the stream at a point where it does flow South. This position is 18.2' South of a straight line between the S.E. & S.W. Sec. Cors. of Sec. 12. There is a fence corner 135' South and about 16' East of this position but it cannot represent the true 1/4 Cor. position because the distance Easterly along a line from the fence corner to the S.E. Sec. Cor. of Sec. 12 is about 140' less than the G.L.O. record to a small stream and crosses the stream at a point where it flows South-*

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

*westerly, not South as recorded. Also, the fence corner is more than 150' South of a straight line from Sec. Cor. to Sec. Cor.

L-5 1" pipe, 4" alum. cap; 12" Oak S17°W 94.2'; 9" Oak S20°E 84.1'; 8" Oak N19°E 118.3'; 9" J. Pine N64°W 13.6'.

SIGNED BY

David B. Babbitt

DATE

12-21-82

SURVEYOR'S MICHIGAN REGISTRATION NO.

21558

(SEAL)