

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____ T. <u>36</u> N. S., R. <u>27</u> E. W.		<u>H-9, I-9</u>
2. PROPERTY CONTROLLING IN SECTION _____ T. _____ N. S., R. _____ E. W.		
3. MISCELLANEOUS PROPERTY IN SECTION _____ T. _____ N. S., R. _____ E. W.		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, **David B. Babbitt** do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on September 2 1980, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

- H-9 South $\frac{1}{4}$ corner - Section 22; Wood Post, Lynn 14 - N26°E - 46 lks.; Sugar 12 - S35°W - 58 lks.
- I-9 S.E. section corner - Section 22; Wood Post, Cedar 14 - N64°E - 11 lks.; Cedar 12 - S52°W - 23 lks.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- H-9 Set in centerline of E-W road and midway between the S.W. and S.E. section corners of Sec. 22. Does not fall on line between the two section corners.
- I-9 Searched for but found nothing. Set monument at centerline of roads north and east and west and in line with a very old fence south.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- H-9 1" pipe, 4" aluminum cap buried in road; 10" W. Birch - N29°W - 23.6'; E. Gate Post - N13°E - 35.6'; 3" W. Pine - S32°E - 29.5'; 12" Triple Hemlock - S43°W - 52.8'.
- I-9 1" pipe, 4" aluminum cap buried in road; 7" Cedar - S23°W - 24.8'; 7" Cedar - S45°E - 37.9'; 7" Tam. - N32°E - 77.7'; 6" Cedar - N26°W - 55.9'.

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY David B. Babbitt DATE 1-26-81
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. 21558