REMONUMENTATION

APR 2 4 1995

in Section

Private Claims ...

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	up Under Act 3	
Poor Gro P.A. Of 1900 Go	12/9	_ 199 <i>94</i>
	EZ Don	11 216

proved by Menomines County

For	corners iCOMMISSION	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			16926		
	MENOMINEE	Located in:	Corner Code ##				
	(County)				14 48 SA		
1.	Public Land Survey	T 36N R 28W	M-10				
	•	T R			0 NE		
		T R					
_		IR			See See		
2.	Property Controlling S_						

Miscellaneous Register of Deeds Stamp & File Number Property in Sec. _ , Recorded Plat _

June 14 William Lenca in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

_ R _

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10 11 12

> MALLIW LENCA LAND

ERED LAND

REVISED MAY 14, 1975

Description of original monument and accessories and/or subsequent restoration:

Original Survey by H. Brevoort - B.T.'s - Hemlock, 4", S79°W, 11 lks & Hemlock, 6", N44.5°W, 27 lks. All original evidence for this corner has been destroyed by farming activities & road improvements.

L.C.R.C. No. 215 recorded by David Babbitt, RLS No. 21558, states that a 1" dia. Iron Pipe/4" aluminum cap was set at 1979: an old gate post on the north side of a driveway and in line with an old fence N-S, based on the testimony of a Mr. Louis Berglin who recalls the corner being established in this position in a 1911 survey." B.T.'s - W. Pine - N190W - 78.55'; Nail & Brass Cap in face of Power Pole - N36°W - 97.35'; Nail & Brass cap in face of P. Pole - S42°W - 117.7'; Centerline N-S Road - West - 101'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found a 1" dia. Iron Pipe/4" dia. Alum. cap (Standard DNR Monument) and B.T.'s as described in L.C.R.C. No. 215 (see part "A"). This location has been accepted as the corner position for 80 years, and is accepted as the best available evidence of the position of the original corner.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found 1" dia. Iron Pipe/4" dia. Alum. cap stamped for corner location (Standard DNR Monument):

N55°W Scr. NBT 165.72 feet N51°E 5/8" x 24" Iron Rod/2" dia. Alum cap (WITNESS MARKER) 5.75 feet S170W 31.57 feet 5/8" x 24" Iron Rod/2" dia. Alum cap (WITNESS MARKER) S590W 196.14 feet Scr. NBT 14" dia. Norway Pine 1.3 feet North Survey Sign Post

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

	y W. aim Joses		Date	Sep. 14, 1994		
Signed	by Comment	4	Duto			٠
^	to Michigan Lineana Mo	00101		THE PERSON OF LAND DUDGENARY	IAM 20	107