

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Menominee</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>37N</u> R <u>25W</u>	<u>J-9, I-9.</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S <u>23</u> T <u>37N</u> R <u>25W</u>	<u>15.</u>
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

I, David Babbitt, in a field survey on 10/1, 19 86,
 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
 in lines 1 and 2 above were in conformance with regulations and rules theretofore as required in the
 current manual of survey instructions of the United States Department of the Interior, Bureau of Land
 Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
 Court of Law; established, re-established, monumented, re-monumented, recovered, found as
 expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded
 on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

J-9. South 1/4 corner of Section 23. DNR Monument. Set 8-8-69 by F. Bray.
 10" Elm S60W, 15½ Lks. 9" Elm S33E, 23½ Lks.

I-9. SW section corner of Section 23. ½"x12" re-rod set 8-8-69 by F. Bray. (DNR)
 9" S.Maple, N74E, 93 Lks. 9" Y.Birch, S64E, 98 Lks.

15. West 1/16 corner on the south section line of Section 23. DNR Monument. Set 8-8-69 by F.
 Bray. 6" Elm N18E, 03½ Lks., 7" Cedar, S12E, 13½ Lks.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

J-9. Found DNR monument in beaver pond--both DNR. NBT's in place but dead and in poor
 condition. Marked four new NBT's.

I-9. Found ½" rod in blk. top road intersection. Both DNR NBT's in place with bearings
 and distances good but the SE one has been cut. Marked three new BT's.

15. Found DNR monument moved. Found both DNR BT's and hole in ground where monument had been
 pulled out. Re-set monument in same hole. The NE BT was dead and down. Marked three
 new BT's.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-9. DNR Monument	I-9. ½" iron rod.
4" Balsam, S62W, 78.8'	Nail & brass tag in side of p.pole.
9" Balsam, S4W, 64.5'	N50E, 48.0'
8" Balsam, N15E, 84.1'	3" Beech, S59E, 70.7'
7" Spruce, N60E, 105.4'	Tele-junct. post N58W, 64.8'
	F. Bray's NBT 10" Y.Birch (stump), S64E, 64.7'
	F. Bray's NBT 10" S.Maple N74E, 61.4'

15. DNR Monument
 5" Maple, N49E, 54.45'
 6" Cedar, S52E, 17.4'
 4" Y.Birch, N32W, 21.5'
 F. Bray's NBT, 8" cedar, S12E, 8.9'

Signed by David B. Babbitt Date 1-27-87
 Surveyor's Michigan License No. 21558

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													