

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

or corners in

Menominee (County) Located In: Corner Code #
Public Land Survey T 41N R 26W D05
T 41N R 26W E05
Property Controlling Section S T R
S T R
Miscellaneous Property in Sec. S T R
S T R

Lot No. Recorded Plat
Private Claims

8/21/2014
Jeremy J. Pipp, in a field survey on 8/13/2014 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(D05) Quarter corner common to Sections 8 and 17. 1852: E.C. Martin, DS. Set quarter section post
witnessed by Cedar 16 S37E 17 links (11.22'), Cedar 14 N50W 9 links (5.94'). No evidence of
subsequent establishment.
(E05) Section corner common to Sections 8, 9, 16, and 17. 1852: E.C. Martin, DS. Set section post
witnessed by Cedar 16 S75W 26 links (17.16'), Cedar 10 N73E 7 links (4.62'). No evidence of
subsequent establishment.

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(D05) No evidence of original survey. Location has been altered by logging activities; corner falls
+/-70 feet West of snowmobile trail road in a recent clear cut. Corner position reestablished by
single proportionate measurement between the Southwest corner and the Southeast corner of Section
8. Position is accepted as a careful and faithful REESTABLISHMENT of the position of the original
corner.
(E05) No evidence of original survey. Location falls in a Larch plantation, thus area has been
plowed and furrowed. Corner position reestablished by double proportionate measurement using
existing corners one & one-half miles North, one-half mile East, one-half mile South, and one mile
West. Position is accepted as a careful and faithful REESTABLISHMENT of the position of the
original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
(D05) DNR monument (E05) DNR monument
6" Poplar N68E 14.81' (1/4S,NBT) 7" Tamarack N65E 4.26' (S9,NBT)
6" Poplar S17E 16.96' (1/4S,NBT) 6" Tamarack S11E 9.87' (S16,NBT)
6" Poplar S50W 6.04' (1/4S,NBT) 9" Tamarack S35W 21.50' (S17,NBT)
7" Poplar N42W 6.34' (1/4S,NBT) 7" Tamarack N75W 11.79' (S8,NBT)
All trees are blazed, scribed, painted, and signed. Measurements are to nail in
side of tree, bearings are magnetic. A Metal sign post was set North 1.5 feet.
Signed by Date August 26, 2014
Surveyor's Michigan License No. 50447

Table with 13 rows and 13 columns (A-M) for Register of Deeds Stamp & File Number. Contains numbers 1-36 in a grid pattern.