LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Menominee (County)	Located In:	Corner Code #		
Public Land Survey	T 41N R 2	6W H05 6W G07		
Property Controlling Section	S T R S T R S T R		91	
3. Miscellaneous Property in Sec.	STR_ STR_		Register of Deeds Stamp	& File Number
4. Lot No, Rec 5. Private Claims	orded Plat3/	18/2014	A B C D E F G 1 2 - 6 - 5 - 4	H I J K L M
above were in conformance with renstructions of the United States D a Court of Law and /or that the co	74, Michigan P.A. of 1970, the egulations and rules therefore as epartment of the Interior, Burelorner points mentioned in lines 3 of Land Surveyors or by a	do hereby state corner points mentioned in lines 1 and s required in the current manual of surve au of Land Management or by a decree of 3, 4 and 5 above were in conformance with Decree of a Court of Law; established	2 4 7 8 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9	15 14 13
NOTE: Not more than 2 corners on this certificate.	ers, all in the same town and	frange, may be recorded	10 30 29 28 11 12 31 32 33	27 -26 -25 - 34 -35 -36 -
A. Description of original mo	onument and accessories a	nd/or subsequent restoration:	13	

(HO5) Quarter corner common to Sections 10 and 15. 1852: E. C. Martin, DS. Set Quarter section corner post witnessed by Tamarack 16 S33W 17 links (11.22'), Tamarack 12 N60E 20 links (13.20'). Squared 15" Cedar tipped out NW.

(GO7) Section corner common to Sections 15, 16, 21, and 22. 1852: E. C. Martin, DS. Set section corner post witnessed by Cedar 16 S43W 8 links (5.28'), Tamarack 16 N42E 28 links (18.48'). 1955: Michigan DNR (Billy Buckler PS#8887) Set 1" pipe with 4" Brass cap from original evidence witnessed by 7" Cedar N88W 28 links (18.48'), 6" Tamarack S83E 29 links (19.14').

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(HO5) No evidence of original survey. Corner position reestablished by single proportionate measurement between the Northeast corner and the Northwest corner of Section 15. Position is accepted as a careful and faithful REESTABLISHMENT of the position of the original corner. (NOTE: Calculated location would fall in the Center of above described Squared 15" Cedar if it were to be standing vertically and not a tip out.)

(GO7) Accepted found Michigan DNR monument, remains of SW OBT, and Two NBT witnesses (Both living). Position is accepted as a careful and faithful PERPETUATION of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5" Cedar N63E 11.15' (1/48,NBT) \$47E 13.53' (1/48,NBT) 5" Cedar 4" Cedar \$34W 10.71' (1/4S,NBT) N51W 24.93' (1/4S,NBT) 9* Spruce All trees are blazed, scribed, painted, and signed. Measurements are to nail in side of tree, bearings are magnetic. A Metal sign post was set North 2.0 feet. demi Surveyor's Michigan License No. 50447

DNR monument

(G07) DNR monument N21E 16.46' (S 15,NBT) 9" Cedar EX 15" Tamarack S78E 18.53' (- , -) S32W 10.94' (\$ 21,NBT) 7" Cedar EX 10" Cedar West 20.22' (- , -) All trees are blazed, scribed, painted, and signod Mide surements are to nail in since tree, begings are magnetic. A Netal sign post was set North 1.5 feet.

JEREMYDite July 9, 2014

PROFESSIONAL

FORM APPROVED BY

Q For the Michigan Department of Natural Resources Ediest Resource Division

20338

(H05)

20339

STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 Revised May 14, 1975

Revised Jan., 1983 Rervised Oct., 1995