LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. PA 1970

	Tilling Requirement of Act 7	4, WIGH. 1 A 1970
For Corners In: Missaukee (County)	Located In Corner Code #	
Public Land Survey	T 21N R 6W J5	
Property Controlling in Section	S T R	
Miscellaneous Property in Section	S T R S T R S T R S T R S T R R S T R R S T T R R S T R R S T T R R S T R R R T R R R T R R R T R R R T R	
4. Lot No:	Recorded Plat:	
5. Private Claims:		
requirements of PA 74, Mic and 2 above were in confo the current manual of sur Interior, Bureau of Land Ma corner points mentioned in of the Michigan Board of	eld survey on August 13, 2014 do hereby state that und chigan PA of 1970, the corner points mentioned in lines mance with regulations and rules therefore as required vey instructions of the United States Department of the unagement or by a decree of a Court of Law and/or that the lines 3, 4 and 5 above were in conformance with the rule Land Surveyors or by a Decree of a Court of Lamonumented, recovered, found as expressed below:	er 1 4 7 8 9 10 11 12 in 5 ne 6 18 17 16 15 14 13 es 7
NOTE: Not more than be recorded on this ce	2 corners, all in the same town and range, may rtificate.	10 -30 -29 -28 -27 -26 -25 11
 A. Description of original monument and accessories and/or subsequent restoration: J5 - 1852 - GLO - W. L. Coffinberry - Set Post 1) Y Pine 16" diam. S26°W 31 L. 2) W Pine 40" diam. S84½°W 34 L. - 1963 - "T. C. Redman Inc. Sub. No. 10" - L. 2 of plats, p. 103 & 104 - P. B. Lapham (PS 9433). ½" x 36" long bar encased in 4" x 36" long concrete cylinder. - 1987 - LCRC # 744 - C. F. Roser - Found and accepted round concrete monument from "T.C. Redman Inc. Subdivision No. 10" and set Cedar post. 3) 9" Oak N36°W 45.10' 4) 8" Oak N40°E 10.87' 5) 7" Maple N75°E 17.83' 		
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:		
post alongside. Fits	to Sections 11 & 14 - Found 4" round concrete mores 1963 plat. Condition of witnesses as follows: #1 tracepted as the best available evidence of the post a	nument with ½" rebar with rotten Cedar post and 6' tall wood & 2 – gone; #3 to 5 are OK. No GLO evidence found. esition of the original comer.
C. Description of monum <u>J5</u> – Epoxied stamped 2"	ent for corner and accessories established to perp aluminum cap onto fd. ½" rebar in the 4" concrete	monument.
N35°E 10.83' to fou N39°W 45.06' to se East 9.56' (9.67' – F	nail & tag in S side 18" R. Maple (#5) nd 40D nail in SE side 15" Oak (#4) t nail & tag in SW side 16" Oak (#3)) to found ¾" outer diameter pinched pipe – Corne comer of block foundation of house #4509 Post 1' Northeast	CRAIG W. MCVEAN PROFESSIONAL SURVEYOR NO. 39088
Signed by: One Surveyor's Michigan L	700,7000	ate: 1/15/2015