LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Missaukee (County)	Located In	Corner Code #		
1. Public Land Survey	T 23N R 7W	B3		
Property Controlling in Section	S T R S			
Miscellaneous Property in Section	S T R S T R		Register of Deeds	Stamp & File Number
4. Lot No:	Recorded Plat:		A B C D E F G	HIJKLM
5. Private Claims:			2 6 5 4	_311
requirements of PA 74, Mic and 2 above were in conforthe current manual of sur Interior, Bureau of Land Ma corner points mentioned in of the Michigan Board of established, re-established,	field survey on July 16, 2007 do he chigan PA of 1970, the corner points rmance with regulations and rules the vey instructions of the United State magement or by a decree of a Court lines 3, 4 and 5 above were in conformant for Land Surveyors or by a Decree monumented, recovered, found as e 2 corners, all in the same town rtificate.	mentioned in lines 1 erefore as required in es Department of the of Law and/or that the rmance with the rules of a Court of Law; xpressed below:	3 4 7 8 9 9 5 5 6 18 17 16 7 7 8 19 20 21 9 10 30 29 28 11 12 31 32 33 13	
A. Description of original	I monument and accessories and	or subsequent restoratio		
3) Hemlock 10" S3: 4) Sugar 12" N79½ - 1967 – LCRC #254 nail on top of existing petition survey by J 5) N10°E 1.70' - 4" 6) N55°E 5.63' - 5" 7) S47°E 17.51' - 7 B. Description of corner B3 – Section ¼ corner or remains North-So ironwood but dead	E 44 7 28 tings BK#35, p. 49 ake . McBain, Petition Survey Sec. 6 33/4°W 19 8°E 49 I, MDOT (MHSD). Placed Brassing 4" Cedar stake as recorded in John D. McBain, County Surveyor Maple Maple "Hickory evidence found and/or method all common to Sections 6 & 7, T23N uth and East-West. GLO & CSR d. ½" iron accepted as the best a	Fd. old st survey by 5) N5°E 6) N75°E 7) S35°E 7 1994 – R - 2000 – R tag and Fd. ½" In 1907 Same With same	take and replaced with ½" y MHSD. 1.69' - 3" Maple 1.5.63' - 4" Maple 1.7.55' - 5" Elm Rec. Survey L. S-3, p. 243 - Rec. Survey L. S-4, p. 125 - por; 3' Tall Steel post adj. to its as LCRC #254. Rec. Survey L. S-4, p. 167 - resses as L. S-4, p. 125 restablishing corner: smooth iron rod, down 1'± a itnesses #5 and #6 in good position of the original cor	- D. E. Schripsema - D. E. Schripsema o comer. - W. E. Sikkema – at intersection of fence d condition, #7 found ner.
B3 – Replaced ½" x 18" Set Blue Carsonite N38°W 2.01' to fou N52°E 5.78' to set S46°E 42.18' to se S30°W 61.65' to se Reset steel fence p	nd nail in Southwest side 9" Suga nail and tag at found nail in South t nail and tag in Northeast side 15 et nail and tag in Northwest side 4 post 1' East	Aluminum DNR cap on 1 ar Maple (#5) neast side 6" Sugar Maple 5" Sugar Maple " Oak	l" x 36" galvanized iron pip	
Signed by: Surveyor's Michigan	ue W. Ma Va Licertse No.: 39088	Date:	11/24/2008	A POFESSIONAL STATE