

JAN 2 2001

## Montmorency County Remonumentation

Liber 00012 Page 0440

## SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MONTMORENCY

(County)

Located In:  
BRILEY TWP.

Corner Code #

1. Public Land Survey

T 30 N R 2 ED-3T RT RT R2. Property Controlling  
in SectionS T RS T R3. Miscellaneous  
Property in Sec.S T RS T RSTATE OF MICHIGAN  
MONTMORENCY COUNTY  
Recorded & Filed

12-05-2000 10:06:03

TERESA WALKER  
REGISTER OF DEEDS

Register of Deeds Stamp &amp; File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

	A	B	C	D	E	F	G	H	I	J	K	L
1												
2	6			5		4			3		2	1
3												
4	7			8		9			10		11	12
5												
6	18			17		16			15		14	13
7												
8	19			20		21			22		23	24
9												
10	30			29		28			27		26	25
11												
12	31			32		33			34		35	36
13												

I, DONALD E MARLATT, in a field survey on MAY, 2000, XX do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

## A. Description of original monument and accessories and/or subsequent restoration:

D-3 1/4 COR. COMMON TO SECTIONS 5 &amp; 8.

G.L.O. COR. WAS SET BY LEWIS CLASON IN APRIL 1840. BEECH 20" N57°W 20 L., BEECH 24" S23°E 27 G.G. SLATTERY P.E. MSHD SURVEY CREW CHIEF IN FEB. 1968 SET A 3/4" X 36" STEERING GEAR SHAFT BY G.L.O. PROPORTION 23' SOUTH TO E & W FENCE AND 57' WEST TO N & S FENCE. NEW 4 STRAND BARB WIRE FENCE EAST AND NORTH. S80°W 15.03' 7" MAPLE, N13°W 6.35' 12" MAPLE LUMP, S45°E 3.53' 5" MAPLE CLUMP.

COUNTY ROAD COMMISSION NOTES (NO DATE) SAME CORNER DESCRIPTION AND WITNESSES AS ABOVE.

D.E. MARLATT P.S. #18660 FILED ACT 132 DATED 2/28/74 IN L.1., P. 555. FD. STEERING GEAR SHAFT NO WITNESSES.

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D-3 1/4 COR. COMMON TO SECTIONS 5 &amp; 8.

FOUND STEERING GEAR SHAFT (3/4" X 36")

S85°W 12" MAPLE 15.03' R.

S55°W 7" TW. MAPLE 25.83'

S12°E 6" MAPLE 17.6'

S45°E 7" MAPLE 20.62'

APPROVED BY  
PEER GROUP

JUL 18 00

J.E.B.

## C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-3 1/4 COR. COMMON TO SECTIONS 5 &amp; 8.

SET CONC. MONUMENT WITH REMON. CAP

N85°W 12" MAPLE 15.03'

S55°W 7" TW. MAPLE 25.83'

S12°E 6" MAPLE 17.6'

S45°E 7" MAPLE 20.62'

WITNESSES MARKED WITH 40 PENNY SPIKES AND P.S. TAGS # 18660.

APPROVED BY PEER GROUP ON JULY 18, 2000 AS THE BEST AVAILABLE EVIDENCE OF THE RE-ESTABLISHMENT OF THE ORIGINAL CORNER.

Signed by Donald E MarlattDate 12/4/2000Surveyor's Michigan License No. 18660