

SURVEY & REMONUMENTATION

JAN 22 2001

Liber 00012 Page 0413

SECTION MONTMORENCY COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Located in:

Montmorency
(County)

Briley
(Township)

Corner Code #

1. Public Land Survey

T 30N R 2E

G-8

2. Property Controlling
In Section

S
S

T R
T R
T R

3. Miscellaneous
Property in Sec.

S
S

T R
T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

STATE OF MICHIGAN
MONTMORENCY COUNTY
Recorded & Filed

10-27-2000 11:57:04

TERESA WALKER
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, Larry G. Beauregard, in a field survey on MARCH, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules thereof as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
G-8 1/4 Corner between Sections 21 & 22.

1840 Lewis Clason, D.S. Marked Tam. 7" for Qr. Sec. Post.

1996 Donald E. Marlatt P.S. #18660, set 1/2" rod & cap by S.P. method. Wit's Mkd. (S15E 6" Cedar 29.88") (S30W 8" Cedar 5.0") (S80W 4" Tamarack 3.03") (N65W 4" Cedar 43.05"). Prepared Act #132 for survey in the SW 1/4 of Sec. 22 (not recorded).

1997 Donald E. Marlatt P.S. #18660, fnd. his previous 1/2" rod & cap & same wit's above. Prepared Act #132 for survey along the line between Sec. 21 & 22. Not recorded.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

March 2000: Fnd. 1/2" rod, cap #18660 & wit's by Marlatt. Re-placed with 4" x 36" concrete monument with a 3/4" aluminum Re-mon. cap.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-8 1/4 Corner between Sections 21 & 22.

4" x 36" concrete monument with a 3/4" aluminum Mont. Co. Re-mon. cap.

Accepted as a careful and faithful establishment of the position of the original corner.

Accepted by the peer group on July 18, 2000.

S15°E 29.88' 6" Twin Cedar
S30°W 5.00' 8" Cedar
S80°W 3.03' 4" Tamarack
N65°W 43.05' 4" Cedar


Placed 60d penny spike & P.S. tag #18654 (typ).

	A	B	C	D	E	F	G	H	I	J	K	L
2												
3												
4	7						10		11			
5												
6	15		17		18		16		14		19	
7												
8	19		20		21		22		23		24	
9												
10	29		28		26		27		25		26	
11												
12	31		32		33		34		35		36	
13												

APPROVED BY
PEER GROUP

JUL 18 00

L.G.B.



Signed by Larry G. Beauregard

Date 10-27-00

Surveyor's Michigan License No. 18654