LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in			
_	Montmorency (County)	Located In:	Corner Code ##
1.	Public Land Survey	T <u>31N</u> R <u>3E</u> T <u>31N</u> R <u>3E</u> T R	A-2 B-1
2.	in Section	T R S 6 T 31N R 3E S 6 T 31N R 3E	10 12
3.	Miscellaneous	S T R	


Register of Deeds Stamp & File Number

_ , Recorded Plat Lot No. Private Claims .

Carl R. Johnson , in a field survey on April 3 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:



- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- A-2 Set in line with and double distance of found 3" bar in concrete for center and E1/8 corner on E-W 1 line Sec 1, T31N, R2E. This point seems to be best evidence for restoring this corner.
- 10 Set midway and on line between 1/4 corner and section corner.
- 12 Set by standard survey procedure for subdividing a section.
- B-1 Set by single proportionate measurement between section corners.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-2 - West 4 Corner

D.N.R. Monument

Property in Sec.

7" Cedar (leaning) N3°E 33.8' 6" Spruce S20°W 29.2'

12 - S1/8Cor on N-S \ Line

Set 5/8" bar & Cedar post 7" Cedar N27 W 10.5' 7" Cedar S86 E 5.6'

6" Cedar S32°E 16.0'

10 - <u>S1/8 Cor on W. Side</u>

Set 1" pipe & cedar post Old fence Cor N65 W 37.4'

Monument fall in small bay of stream No other witnesses near cor.

B-l - N≯ Corner

6" Cedar S20°E 25.6' 10" Cedar S89°W 61.4'

Signed by Surveyor's Michigan License No. _____30083

VSEO LAND BOARD OF LAND SURVEYOR RVEYORS, JAN. 20, 1071 REVISED MAY 14, 1975 REVISED JAN., 1983

MHHH

JOHNSON LAND

URVEYOR