

MAR 0 2 1999

recovered, found as expressed below:

1998 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

'99 FEB 17 PM 3 38

SECTION	FILING REQUIREMENT of Act 74, Mich. P.A. 1970			0
For corners in Newaygo (County)	Located in:	Corner Code#	Linsa Y.	n. Brown
1. Public Land Survey	T <u>13N</u> R <u>14W</u> T R T R T R	<u>E-13</u>	vol. 2	211
Property Controlling in Section Miscellaneous Property in Sec.	STR STR STR STR		Register of Deeds Stamp & I	File Number
4. Lot No, Reco	rded Plat		A B C D E F G H 2 - 6 - 5 - 4 - 3 3	I J K L M
do hereby certify that under requipoints mentioned in lines 1 and 2 therefore as required in the curr Department of the Interior, Bure Law and/or that the corner poconformance with the rules of	_ , in a field survey onMay 13 lirements of P. A. 74, Michigan P. 2 above were in conformance with ent manual of survey instructions au of Land Management or by a ints mentioned in lines 3, 4 an the Michigan Board of Land lished, re-established, monumer	A. of 1970, the corner regulations and rules of the United States decree of a Court of d 5 above were in Surveyors or by a	$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	14 - 13 -

Note: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Southwest Corner, Section 33, Dayton Township, Newaygo County, Michigan.

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Mullett and Brookfield 1837 14" Beech N42°E 43 Links (28.38')#1 10" Beech N23°E 55 Links (36.3')#2 Northwest Corner, Section 4, T12N R14W, East 30 Links (19.80')#3

Lyle S. Shepherd R.L.S. #503 Book 47 Pages 80 and 81 April 11, 1916 Gas Pipe and Rock

County Surveyor's Witness Book Page 168 Sleigh Shoe in place of old Government Corner (31/2 feet long) Stone 11/2" feet long 6" X 8" wide, by Sleigh Shoe for Corner. Pump Southwest 68.4' #4 Corner Barn Northwest 67.5' #5

29

32

28

33

26

Sammy S. Barnett R.L.S. #16923 April 27, 1973 LCRC #184 Found 3/4" Pipe Telephone Pole N51°E 72.51′ #6 Power Pole S44°W 52.92' #7 Northeast Corner, Section 5, T12N R14W East 19.85' #3

11

12

13

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found ¾" X 7" Iron Pipe in monument box. The centerline of the East and West bituminous road is 4 feet ± North and the enterline of the bituminous road going North is 4 feet ± East. The condition of the recorded witnesses are: #1 and #2 gone, #3 found Axel Shaft, #4 and #5 gone, #6 and #7 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed Iron Pipe and monument box and set a 23/1" X 20" Harrison cast iron monument marked "County Survey" in a new 8" diameter monument box as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

Northwest Corner, Section 4, T12N R14W (23/2" X 20" Harrison cast iron monument in monument box) East 19.93' #3

Telephone Pole NSO'E 72.15 Set spike with tag #22455 in vi	
Power Pole S40°W 52.72' Found spike with tag #22439 in No	orthwesterly side of pole. #7
Concrete Curb S33°E 61.94' Found P.K. nail in seam of curb.).
6" Cherry N40°W 77.30' Found spike in Easterly side of tree.	•
Signed by Horman L. Ochs	DateOctober 15, 1998
Norman L. Ochs	" Minney William Committee of the Commit
Surveyor's Michigan License No. 22439	Form approved by Michigan State Board of Land Surveyors year 28, 197
Approved by Peer Review Group on October 22, 1998 Norman L. Ochs, County Representative.	NORMAN Revised Jan., 198
Number C. Ooms, County representative.	# CF I OCHS ★★%