SLIEVEY & REMONUMENTATION

MAY - 1 1995

LIBER 15288 PG 527

Mar 1095040441

OK - T. SMITH

800	٦N	ħ.			OF	V
J. 5	HV	ιv	1 i	5 cm 3	₩ .	¥

LAND CORNER RECORDATION CERTIFICATE

Foi	Corners in	Oakland	HI	Commerce		10 MAI	R 95 4:04 1	G – IN H P.M.	IOUSE RECE	IPT# 1	778
	(Coun	ly)	Located	ш.	Corner Code ##	PAID LYNN :	REC D. ALLEN, C	ORDED - Lerk/reg			
1.	Public Land	Survey	T	R	E-1	_ _ APPROVE	Compliance with ACT 345, P.A. 1990 APPROVED ON: 12-27-94 OAKLAND COUNTY REMONUMENTATION PEER GROUP COMMITTEE				
2.	Property Cor in Section					- р					
3.	Miscellaneou Property in S			_ R		Registe	er of Deeds	Stamp &	k File	Numb	er
4.	Lot No	, Record	ed Plat								
							A B C D	E F (3 H	J	<u>K L 1</u>
in I cur Mai abo Cou exp	hereby certify the ines 1 and 2 at the ines 1	bove were in confo survey instructions a decree of a Court formance with the re tablished, re-estab	ents of P.A. 74, rmance with r of the United of Law and/or ules of the Mic olished, monu	Michigan P.A. of 19 egulations and rul States Departmen that the corner poi higan Board of Lar imented, re-monu	70, the corner points les therefore as required to fithe Interior, Burents mentioned in line and Surveyors or by a limented, recovered,	mentioned bired in the eau of Land 5 a Decree of a found as	7 8	16	—10——15———22———27——	11	132425
	on this	certificate.				12 13	- 3,	33	34	35	36-
A.	Description (ot original monum	nent and acc	essories and/or	subsequent restor	ration:					
	n/a	n/a	County records	M. Baldwin	n/a	FB17A-P28					
	197	2 Set 3/4" iron pipe	Survey	G. Kattouah	#14095	L5998 P557					

1991 1/2" Iron L.C.R.C. A. Nicolaescu #22705 L12163 P037 L13026 P47 1992 Set 1/2" iron L.C.R.C. D. Smith #33140 Description of corner evidence found and/or method applied in restoring or reestablishing corner;

G. Kattouah

A 1/2" iron rod at the base of a metal fence post in standing water of a marsh currently marks this corner. The following witness ties were used to recover and verify its position:

3 ties match L.C.R.C. L13026 P47

Survey

1972 Found 3/4" iron

3 ties match L.C.R.C. L12163 P37

Trace of E-S wood and wire fence $\pm 23^{\prime}$ south from M. Baldwin ties

A search has been made ± 7 east of the existing found iron for a possible corenr as referenced to M.

#14095

L5998 P558

Baldwin survey. Nothing found.

Field m	neasurements v	vere made l	between the foll	owing corners:
D-1 to E-1	2562.70	meas.		
	2567.01	rec.	Survey	L8090 P615
	2563.46	rec.	Plats	L223 P10
E-1 to E-2	2897.14	meas.		
	2897.27	rec	Survey	L5998 P557
	2892.78	rec.	G.L.O.	Notes

17632

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1.00 2.00

#16H16

DAVID

PAWLACZYK LAND JRVEYOR NO.

17632

CAND

I replaced the 1/2" iron rod with a 5/8" x 24" iron rod with a 2" diameter brass disk stamped "Oakland County Remonumentation P.S. #17632" with a metal witness post.

S.45° E. 39.21' P.K. nail and O.C.R. tag S.W. face 30" Maple S.35° E. 32.211 P.K. Nail and O.C.R. tag Twin Maple S.07° E. 28.28' P.K. nail and O.C.R. tag W. face 22" Oak S.30° W. P.K. nail and O.C.R. tag E. face 24" Oak 33.65

The selected location is accepted by me and generally accepted by Professional Surveyors as the best a

evidence of the position of the original corner. Signed by

Date 2 -1 Co -95

Surveyor's Michigan License No. .