

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Oakland

Located In: Corner Code #
West Bloomfield Township

1. Public Land Survey

2. Property Controlling in Section

3. Miscellaneous
Property in Sec.

4. Lot No. _____, Recorded Plat _____

5. Private Claims

1. Huston K. Kennedy, in a field survey on January 30, 1988 o hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

NOTE: Not more than 2 corners, all in the same section, may be restored on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
1817-GLO Carpenter, D.S.; Set Post 12" Black Oak S42°W 37 Links; 3" Black Oak N58 ½°E 56 Links

1817-GLO Carpenter, D.C. 13

Oak N58 1/2° E 56 Links

1.) 1972-Landini, PS #16933; LCRC L.5908, pg.595 - Fnd a Monument Box

2.) 1978-Jones, PS #16045; LCRC L.7177, pg.605 - Fnd a Monument

3.) 1979-Lippincott, PS #25855; LCRC L.7447, pg.196 - Fnd a Concrete Monument in a Monument Box

4.) 1992-Kohn, PS #26459; LCRC L.13195, pgs.668 & 669 - Fnd a 1/2" Re-rod in a Monument Box (Con't. on back side of LCRC)

5.) 1973-Kostecke, PS #12584; L.6036, pg.533 - Fnd a Monument Box

Notes: 1. If no evidence found and/or method applied in restoring or reestablishing corner:
2. If no evidence found and/or method applied in restoring or reestablishing corner:
3. If no evidence found and/or method applied in restoring or reestablishing corner:
4. If no evidence found and/or method applied in restoring or reestablishing corner:
5. If no evidence found and/or method applied in restoring or reestablishing corner:

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 1992-Kohn, PS #26459; LGR L 10135, pg. 533 - Find a Monument Box
 1973-Kostecke, PS #12584; L 6036, pg. 533 - Find a Monument Box in the existing centerline of Lochs
 1998-Kennedy Surveying, Inc. - Kennedy, PS #17623 - 1/2" Iron Rod in a Monument Box in the existing centerline of Willow R
 Road extending to the North, which has a bituminous surface, and 1.00 feet North of the existing centerline of Willow R
 Road extending to the East & West, which has a bituminous surface.

Witnesses from LCRC #4 were used to recover and verify the location of the found 1/2" Iron Rod in a Monument Box.

FIELD MEASUREMENTS BETWEEN

D-3 TO C-3

D-3 TO C-3
GLO = 40.145 chains or 2649.57 Ft.
"WILLOW FARM SUBDIVISION" + Parcel (Sec 5) = 2662.49 Ft.
"WILLOW POND" + "BLOOMFIELD ESTATES (Sec 8)"
= 2662.48 Ft. & 2663.35 Ft. (GPS-MEA)

D-3 to E-3

D-3 to E-3
GLO = 40.145 chains or 2649.57 Ft.
"MISSION SPRINGS AT DARB LAKE" + Parcels (Sec 5) = 2672.58 ft.
"BLOOMFIELD POLO ESTATES" + "WILLOWING HEIGHTS" +
"SUPERVISOR'S PLAT NO. 5" + Parcels (Sec 8) = 2672.58 Ft. &
2303.08 Ft. (GPS-MEA to M.C.) + 368.70 Ft. from plats = 2671.78 Ft.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
D-3 I replaced the found $\frac{1}{2}$ " Iron Rod with a $\frac{5}{8}$ " x 24" Iron Rod w/2" diameter brass cap stamped Oakland Co
Remonumentation, PS #17623 in a existing Monument Box
N29°W 95.81' Set PK & Remon Washer NE face Power Pole
N67°E 101.05' Set PK & Remon Washer South face Power Pole
Due South 30.85' Set PK & Remon Washer East face Light Pole
N66°W 104.35' Set PK & Remon Washer South face 18" Locust
South 59.96' Found 4" diameter Concrete Monument

The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.

Date 3-6-98

17623
LICENSED PROFESSIONAL SURVEYOR

Signed by:

Surveyor's Michigan License No. 10000

Date 3-6-78

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYOR'S, JAN. 28,
REVISED MAY 14,
REVISED JAN.,
REVISED OCT.,