LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

-0"	corners in	rang nequire	ement of Act 74, Mich. P.A. 1	310
	Oakland	Located In:	Corner Code ##	
	(County)	Located In:	Corner Code ##	
1.	Public Land Survey	T 4N R 9E	K-5	
		T R T R		Compliance with ACT 345, P.A. 1990
		Ť R		APPROVED ON: 9-27-95 m 5
2.	Property Controlling	S T R		OAKLAND COUNTY REMONUMENTATION
	in Section	S T R		PEER GROUP COMMITTEE
	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
4.	Lot No,	Recorded Plat		ABCDEFGHIJKLM
5.	Private Claims			
				3
				4 7 8 9 10 11 12
		_ , in a field survey on		5
		equirements of P.A. 74, Michigan P.A. o in conformance with regulations and		
curr	ent manual of survey ins	tructions of the United States Departi	ment of the Interior, Bureau of Land	7
	•	of a Court of Law and/or that the corner with the rules of the Michigan Board of	· ·	20-12-22-23-24
Cou	rt of Law; established,	re-established, monumented, re-m		*
•	ressed below:		d	10 30 29 28 27 26 25
NO	on this certificat	corners, all in the same town an	a range, may be recorded	12 31 32 33 34 35 36
		-		13
	,	I monument and accessories and	/or subsequent restoration:	
	Post set in 181	•	•	
	9" R. oak N 55 18" W. oak Sout			\$ 7.00 MISCELLANEOUS RECORDING \$ 2.00 RENONUMENTATION 29 SEP 93 7:30 A.M. RECEIPTH 3B
				PAID RECORDED - DAKLAND COUNTY LYNN D. ALLEN, CLERK/REGISTER OF DEEDS
	Recovered 3/8"	evidence found and/or method a rerod on side of hill. e corner. Corner confir a Park Country Club" sub rds, and survey west of	There are no occupation	LYNN D. ALLEN, CLERK/REGISTER OF DEEDS hing corner: on lines
	Recovered 3/8"	rerod on side of hill.	There are no occupation	LYNN D. ALLEN, CLERK/REGISTER OF DEEDS hing corner: on lines
C.	Recovered 3/8" running from th in the "Thendar. P 40, O.C. Reco Description of monum Set concrete mo	rerod on side of hill. e corner. Corner confir a Park Country Club" sub rds, and survey west of nent for corner and accessories e	There are no occupation med with monumentation odivision recorded in I subdivision by Kieft F	LYNN D. ALLEN, CLERK/REGISTER OF DEEDS hing corner: on lines a found 38, Engineering. JAMES J. SCHARL PROFESSIONAL SURVEYOR NO. 19843 ng the position of the corner:
C.	Recovered 3/8" running from th in the "Thendar. P 40, O.C. Reco Description of monun Set concrete mo N 35°E 17.65' N 10°E 7.92' S 89°E 14.34'	rerod on side of hill. e corner. Corner confir a Park Country Club" sub rds, and survey west of	There are no occupation med with monumentation odivision recorded in I subdivision by Kieft F subdivision by Kieft	LYNN D. ALLEN, CLERK/REGISTER OF DEEDS hing corner: on lines a found 38, Engineering. JAMES J. SCHARL PROFESSIONAL SURVEYOR NO. 19843 ng the position of the corner:
C.	Recovered 3/8" running from th in the "Thendar P 40, O.C. Reco Description of monum Set concrete mo N 35°E 17.65' N 10°E 7.92' S 89°E 14.34' S 10°E 8.31' The selected lo surveyors as th	rerod on side of hill. e corner. Corner confir a Park Country Club" sub rds, and survey west of ment for corner and accessories e nument with remonumentat PK/remon tag SW face 14" PK/remon tag SF face 16" PK/remon tag SW face 18" cation is accepted by the best available evidence	There are no occupation med with monumentation odivision recorded in I subdivision by Kieft Paragraphic Stablished to perpetuate location brass cap, replaced hickory ash ash oak see Contractor and is getter of the position of the contractor of th	LYNN D. ALLEN, CLERK/REGISTER OF DEEDS hing corner: on lines a found 38, Engineering. JAMES J. SCHARL PROFESSIONAL SURVEYOR NO. 19843 ng the position of the corner:
C.	Recovered 3/8" running from th in the "Thendar P 40, O.C. Reco Description of monum Set concrete mo N 35°E 17.65' N 10°E 7.92' S 89°E 14.34' S 10°E 8.31' The selected lo surveyors as th	rerod on side of hill. e corner. Corner confir a Park Country Club" sub rds, and survey west of ment for corner and accessories e nument with remonumentat PK/remon tag SW face 14" PK/remon tag SF face 16" PK/remon tag SW face 18" cation is accepted by the best available evidence	There are no occupation med with monumentation odivision recorded in I subdivision by Kieft Paragraphic Stablished to perpetuate location brass cap, replaced hickory ash ash oak see Contractor and is getter of the position of the contractor of th	LYNN B. ALLEN, CLERK/REGISTER OF DEEDS hing corner: on lines a found 38, Engineering. JAMES J. SCHARL PROFSSSIONAL SURVEYOR NO. 19843 ing the position of the corner: ang 3/8" rerod. Professional This corner