

LIBER 14960 PC 093

MAY - 1 1995

94 242423

OK - 1000000

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Oakland

(County)

Located In: Brandon
Township

Corner Code ~~##~~

1. Public Land Survey

T 5 N R 9 E

H-1

T _____ R _____

T _____ R _____

T, _____ R _____

T _____ R _____

T _____ R _____
I _____ O _____

1	_____	R	_____
T	_____	D	_____

2. Property Controlling in Section

S

S

§

S

3. Miscellaneous Property in Se

§

S

4. Lot No. _____, Recorded Plat _____

5. Private Claims

I, Huston K. Kennedy, in a field survey on October 27, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1817 GLO - Wampler, D.S.; Set post; No witnesses recorded
1973 Henderson, P.S. #16043; LCRC L.6113, Pg.127-128 - Set iron rod
1974 Kennedy, P.S. #17623; LCRC L.6293, Pg.655-656 - Fnd 3/4" iron pipe
1974 Kennedy, P.S. #17623; Survey L.6314, Pg.736-737 - Same wits as 1974 LCRC
1986 Kobs, P.S. #14097; Survey L.9556, Pg.121-122 - Fnd 1/2" iron rod
1986 Kobs, P.S. #14097; LCRC L.9700, Pg.834 - Same wits as 1986 survey
1991 Kennedy, P.S. #17623; LCRC L.12168, Pg.646 - Fnd 1/2" iron rod

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1993 Kennedy Surveying, Inc. - Huston Kennedy, P.S. #17623 - Found a 1/2" iron rod that is 25' South of the center of Fish Lake Road, which is gravel, in an East-West fence line. The witnesses from the 1991 LCRC are still existing. They were used to recover and verify the found 1/2" iron rod. Found a Department of Natural Resources concrete monument with cap 26.20 feet West of the corner.

I accepted the found 1/2" iron rod as the best evidence of the original corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-1 I replaced the found 1/2" iron rod with a 4" diameter concrete cylinder 36" long with a 2" diameter brass cap stamped Oakland County Remonumentation P.S. #17623.

N59°E-14.15 ft-Set P.K. & Remon. Tag above existing witness SE face 11" Maple
N42°E- 7.44 ft-Set P.K. & Remon. Tag above existing witness SE face 10" Maple
N64°W-20.92 ft-Set P.K. & Remon. Tag above existing witness NE face 11" Maple
S74°W-19.70 ft-Set P.K. & Remon. Tag South face 6" Maple

The selected location is accepted by me and is generally accepted by Professor [redacted] as the best available evidence of the position of the original corner.

Signed by

Date April 4, 1994

Surveyor's Michigan License No. U 17623

FORM APPROVED BY MICHIGAN STATE BOARD