## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	
Osceola Located In: Corner	Code #
1. Public Land Survey TR	<u></u>
T R  2. Property Controlling S 3 T 17N R 9W in Section S 34 T 18N R 9W  3. Miscellaneous S T R Property in Sec. S T R	2 16 Register of Deeds Stamp & File Num
4. Lot No, Recorded Plat	
I, <u>Craig W. McVean</u> , in a field survey on <u>Dec. 9</u> , 19 <u>97</u> hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the points mentioned in lines 1 and 2 above were in conformance with regulations rules therefore as required in the current manual of survey instructions of the States Department of the Interior, Bureau of Land Management or by a decree Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above in conformance with the rules of the Michigan Board of Land Surveyors or by Decree of a Court of Law; established, re-established, monumented, recovered found as expressed below:	s and B 19 -20 -21 -22 -23 -24 - 3 of a
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	
A. Description of original monument and accessories and/or subsequent restoration:	
2 - LCRC L. 2, P. 12 - K. J. Ostling - 1977 Set DNR Mon. & Cedar Post 10" Maple in Clp3 S80°E 37.4' 17" W. Oak S20°W 48.4' E-W Random Due N. 9.6' E 1/16 on S. Line 34, T18N, R9W Due W. 31.9'	16 - LCRC L. 2, P. 6 - K. J. Ostling - 1977 Set 5/8" Rod w/cap and Cedar Post 12" Maple N40°W 38.4' 4" Cherry N65°E 34.6' E-W Random Due N. 9.4' E 1/16 on N. Line Sec. 3, T17N, R9W Due E. 31.9' - Rec. Survey - L.562, P. 654 - FND. DNR Corner - J. S. Fokens - 1992
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:	
2 - E 1/16 on N. Line of Sec. 3, T17N, R9W. FND. Capped 5/8" Rebar w/cedar post 0.7' SSE as recorded by KJO. BT's had been cut. Monument fits section Sub and is accepted as a careful & faithful establishment of the corner.	<ul> <li>E 1/16 on S. Line of Sec. 34, T18N, R9W</li> <li>FND. Capped 5/8" Rebar with cedar post 0.9' SE as recorded by KJO. BT's had been cut.</li> <li>N 32.5' to deer fence cor. N&amp;W. Monument</li> <li>Fits Sec. Sub. and is accepted as a careful &amp; faithful establishment of the corner.</li> </ul>
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:	
2 - DNR capped 5/8" Rebar Add Blue Carsonite Post 1'N S57°E 8.51' to N&T in NE Side 5" R. Maple N40°W 9.39' to N&T in SW Side 6" R. Maple N85°W 14.30' to N&T in S. Side 6" R. Maple West 31.94' to Capped 5/8" Rebar	6 - DNR Capped 5/8" Rebar Add Blue Carsonite Post 1'NE S6°W 37.10' to CL. Mon. Box N18°W 20.87' to FND. N&T #21567 in E. Side Tri. 15" R. Maple N40°E 37.39' to N&T in NW Side 5" R. Maple East 31.94' to Capped 5/8" Rebar.
Signed by Crie W. Me Hen	4/27 ** CRAIG W 1
Surveyor's Michigan License No. 39088 PROFESSIONAL SURVEYOR No. 39088	
FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL INVEYORS, JAMES 1855	