## SURVEY & REMONUMENTATION:

DEC 1 3 2000

SECTION

## LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, Mich. P.A. 1970

	corners in	L	ocat	ted in:	Corner Coo	le#					00 001	REGIE	08850
1.	Public Land Survey		T 19 N		R9 W	K-4				: ``	المستنب المدينيو		jĘ.
			<u>T</u>		R						Er		166 255
			Ţ	- 	R						n Ti	<b>?</b>	
			Т		R					1	<u> </u>	ο,	7.4
2.	Property Controlling in Section	s	т_	R									
		S		R			Registe	r of D	ahaal	Stam	n & F	ile Ni	ımher
3.	Miscellaneous Property in Sec.	s	_T	R			registe	. 01 0	eeus	Otani	р с.		
		<u>s</u>	_ I	R								¥ ¥/	
			at				1						LM
i, j	Robert L. Wetherell, in a	2 3	6	5	4	3	2						
hei	reby certify that under reints mentioned in lines 1	4 5	7	8	9	10	11	12					
rule	es therefore as required	6 7	18	17	16	15	14	13					
Co	States Department of the Interior, Bureau of Land Management or by decree of a Court of Law and/or that the comer points mentioned in lines 3, 4, and 5 above were								20	21	22	23	24
In conformance with the rules of the Michigan Board of Land Surveyors or by a Decree Of a Court of Law; established, re-established, monumented, re-monumented,								30	29	28	27	26	25
recovered, found as expressed below:							11 12	31	32	33	34	35	36
<u>K-</u>	K-4 - ¼ Corner common to Sections 11 & 12, T19N, R9W												

A. Description of original monument and accessories and/or subsequent restoration:

1838 - S. Sibley, G.L.O.

#1 - 10" Hemlock S6°W 12 Links #2 - 14" Hemlock N55°W 12 Links

....

1892 - A.O. Temple, Co. Sur. Remonumentation of T19N, R9W

"Found accessory #1 dead with marks on it".

Set 3" Clay Tile.

#3 - 30" Pine Stump S35°E 74 Links

#4 - 26" Pine stump S21°W 64 Links

Undated Co. Sur. Twp. Notes

Pipe and Tile.

#5 - 20" Pine West 12.2'

#6 - 6" Hemlock N15°E 90'

#7 - Distance South = 2616.8'

1988 - R.L. Wetherell, LS 24624

L.C.R.C. - Liber 02, Pg. 305.

"Found 2" Pipe and Tile".

Set 1/2" Iron in 2" Pipe.

#5 - 48" W. Pine S84°W 13.10'

#8 - 8" Elm N81°E 50.63'

#9 - 14" Maple S20°W 20.60'

B. Description of corner evidence found and/or method applied in restoring of reestablishing corner:

I found a ½" Capped rebar (LS 24624) inside a 2" pipe which is inside the 3" Clay Tile (broken). The corner is in line with an old fence to the West and at the extension of centerline of seasonal roads North and East.

Condition of the accessories are as follows: #1 Gone, #2 Gone, #3 Gone, #4 Gone, #5 Found in good condition (50"), #6 Found in good condition, #7 Measured 2617.62' #8 Found dead, #9 Found in good condition.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I placed a 1" x 18" Pipe with an Osceola County Remon Cap in the center of the 2" pipe, and is accepted as a careful and faithful perpetuation of the position of the original corner.

16" Hemlock N15°E 91.1' (center of tree) #6

16" Maple S20°W 20.51' (60d spike in E. side) #9

18" Maple N18°W 77.84' (60d spike in E. side)

5" W. Pine N45°E 61.12' (60d spike S.E. side)

10" Maple (in clump) S23°E 72.84' (60d spike W. side)

APPROVED LAND CORNER P.A. 345 OF 1990 Osceola County

17-00

ed by Robert L. Wetherell

Date August 22, 2000

Surveyor's Michigan License No. 24624

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN.28, 1971 REVISED MAY 14, 1975 REVISED JAN. 1983

65 813m 74

CARDEN !

2,5833

WEYO