

SURVEY & REMONUMENTATION

APR 24 1995

OTTAWA COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

94 DEC 15 AM 11:45

COMMISSION

For corners in

OTTAWA (County)

Located In:

Corner Code ##

- | | | | | | |
|------------------------------------|---|----|---|-----|------------------------------|
| 1. Public Land Survey | T | 8N | R | 16W | G-12, E $\frac{1}{2}$ Corner |
| | T | | R | | Section 33 |
| | T | | R | | Spring LAke Twp. |
| | T | | R | | |
| 2. Property Controlling in Section | S | | T | R | |
| | S | | T | R | |
| 3. Miscellaneous Property in Sec. | S | | T | R | |
| | S | | T | R | |

Register of Deeds
REGISTER OF DEEDS
OTTAWA COUNTY, MI

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, THOMAS E. JOINER in a field survey on 11-29- 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

05-26-1832	Liber 1, Pg. 349, 04-10-72
Post set by John Mullet, D.S.	Found steel plug
N12°E 19 8" Pine	NE 54.68 Nail in face of Guy pole
S35°W 6 Brown Ash	WSW 36.51 Nail in face of Light pole
	W. 3.50 West edge of pavement
	S. 119.24 PK
	SSW 89.73 NE edge culvert wall
	SE 34.00 E Manhole

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found PK nail and accepted as a careful and faithful perpetuation of the position of the original corner based on the following:

Prein & Newhof witnesses per Job No. 93327
N45°E 55.60 Fnd. Doublheaded Nail NW side Guy Pole
S60°E 82.78 Fnd. PK in Side Power Pole
West 2695.21 FCI in Mon. Box Center Sec. 33-8-16, F-12

Joiner Engineering Inc. Job No. 1046
Distance measured to SE cor. Sec. 33-8-16, G-13
Job No. 1046 Dist = 2681.24 MI Remon. Dist = 2681.28

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced PK Nail with Cast Iron Monument in Monument Box placed my Materials Testing.

Top Operating Nut on Hydrant	Az.	39°	61.13
O.C. Remon. Tag & Nail in N side Power Pole	Az.	114°	82.73
O.C. Remon. Tag & Nail in NW side 16" Maple	Az.	234°	95.55
Cut cross W. end 30" Conc. Culvert	Az.	245°	92.59

P.A. 345 OTTAWA COUNTY

PEER APPROVED

12/12/94
Rocky D. Nedwell
12-12-94

Signed by Thomas E. Joiner

Date

Surveyor's Michigan License No. 18435

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197
REVISED MAY 14, 197
REVISED JAN., 191