LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

St Joseph County Remonumentation For corners in LIBER 6 PAGE 86 Located In: Corner Code # St. Joseph STATE OF MICHIGAN (County) ST. JOSEPH COUNTY 1. Public Land Survey T 5S R<u>12W</u> FILED R R 1/3/2001 12:02:25 PM R SURVEY & 2. Property Controlling CYNTHIA L. JARRATT in Section S Т REGISTER OF DEEDS 3. Miscellaneous T R JAN 31 2001 Register of Deeds Stamp & File Number Property in Sec. SECTION _ , Recorded Plat _ 5. Private Claims 1 2 3 10 --- 11 --- 12 --4 DALE L. KESLER in a field survey on JULY 5, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned 5 in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the 6 ...15 current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed Я -22 - 23 - 24 NOTE: Not more than 2 corners, all in the same town and range, may be recorded 1.0 27 26 - 25 on this certificate. 11 -34---35 i - 36--i A. Description of original monument and accessories and/or subsequent restoration: GLO Dec. 1830 1876 and 1878 Norman Andrews Set post stone from original bearings 20" Beech S 39 deg W 35 (23.1') Book A, Pg 218 & 219 18" W. Oak N 66 deg W 40 (26.4') RATIFIED BY PEER GROUP 1898 September - Victor Rodd Found stone marked (+) in line of IN ACCORDANCE WITH P.A. 345 fences set by former surveyor. Set short Nov. 13 . 2000 stake above stone CO. REPRESENTATIVE 12" Maple N 74 deg 15' W 9.345 ch (22.77') 7" Walnut S 11 deg 45' E 1.695 ch (111.87') Description of corner evidence found and/or method applied in restoring or reestablishing corner: Did not find corner. Road has new pavement, met with Road Commission dug in this area, did not find corner. Corner was reestablished by single proportionate measurement using the Northeast corner of Section 6 and the Southeast corner of Section 6 of Flowerfield Township. Description of monument for corner and accessories established to perpetuate locating the position of the corner: \mathbf{C} Set a 5/8" x 24" iron rebar with aluminum cap in a monument box and is accepted as a careful and faithful reestablishment of the position of the original corner. Vail w/ tag 28" Oak S 15 deg 42' W 95.13' Vail w/ tag wood fence post N 86 deg 02' W 27.93' Vail w/tag 28" Maple N 07 deg 18' W 185.60' 3W corner of two story brick house N 17 deg 15' E 257.68' 3igned by 38117 Surveyor's Michigan License No. DALE 1 FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 * LAND SU. No. 38117

AND SURFFIRM REVISED MAY 14.1975

71

REMONIMENTATION