

SCHOOLCRAFT COUNTY  
PEER GROUP APPROVED

DATE March 10, 1995 LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

OCT 26 1995

COMMISSION

For corners in  
Schoolcraft  
(County)

Located In: Corner Code #

1. Public Land Survey	T 42N R 15W	F3
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Received & Filed this 10 day of March 19 95 at 2:36 P M  
Sigrid I. Hedberg  
Schoolcraft Co. Reg. of Deeds

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on February 08, 1995, 19\_\_\_\_\_, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:  
(F3) Quarter corner common to Sections 4-9. Corner established in 1850 by Algernon Merryweather. Accessories were Balsam 7 S54E 17, Balsam 6 N60W 4. Corner record filed in 1991 by Gerald L. Wiggins RLS #23521 as follows: Corner set midpoint on line between NW Section Corner and NE Section Corner of Section 9. Placed DNR monument, 10" Maple N35E 9.9', 6" Y. Birch N32W 10.3', 8" Y. Birch S82W 23.6', 8" Maple South 12.15'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  
(F3) Original post and accessories not recovered. Found no acceptable evidence of the position of the original corner on the ground. Recovered the 1991 monument as described, in good condition, and at record bearing and distance from the 1991 accessories. I determined that the 1991 corner position is erroneous, pursuant to the Jan. 18, 1995 remonumentation of the corner E3 by the undersigned. I reestablished the corner midway and on a straight line between E3 2649.74' west and G3 2649.74' east. At the position for the corner, I placed the 1991 monument, a 1" I.D.x36" iron pipe capped with a 4" dia. cast aluminum MDNR tablet, appropriately stamped. I defaced and cut down the 1991 10" Maple witness but left the others standing and undefaced, their markings still facing the remonumented corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F3) Placed a 1" I.D. iron pipe with 4" MDNR cap. Placed measuring nails with ref. tags in the 1991 accessories:  
8" Y. Birch N54W 17.55' w/ old marks  
8" Y. Birch West 32.95'(slope)  
8" Maple S40W 15.2'(slope)  
Marked a new BT:  
8" Balsam N65W 7.05' "1/4S N8T"  
Wood post with Schoolcraft County Survey poster affixed is adjacent. Bearings are magnetic.



Signed by Stephan J. Szyszkoski Date 2-28-95  
Surveyor's Michigan License No. 33986