

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft (County)	Located In:	Corner Code #
1. Public Land Survey	T 43N R 15W	G7
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S 16 T 43N R 15W	12
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on G7 02/13/2012 do hereby state
12 02/16/2012
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(G7) Corner common to Sections 15-16-21-22. 1973 - Frank J. Bray RLS reestablished the corner by
double proportionate measurement between corners 1 mile north, 1 mile south, 2 miles west, and 1/2
mile east. Set 1"ID iron pipe with 4" alum. cap. 8" J.Pine N73W 41.2', 6" J.Pine S45E 6.5'.

(12-Sec. 16) South 1/16 corner. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(G7) Found the 1973 monument of record in good condition and at record bearing and distance from the
1973 witnesses, now both stumps. Accepted the monument as a careful and faithful reestablishment of
the position of the original corner.

(12-Sec. 16) Established the position for the corner midway and on a straight line between Quarter
corner 1326.54' south and the intersection of 1/4 lines of Section 16 1326.54' north.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(G7) Fd. 1"ID I.pipe with 4" alum. MI Dept.
of Conservation cap.
Set measuring nail with MDNR tag in the side of:
12" J.Pine S14E 20.0' mrkd "S22 NBT"
12" J.Pine S60E 23.35' "S22 NBT"
6" J.Pine N38E 7.85' "S15 NBT"
5" J.Pine N88W 8.9' "S16 NBT"
Bearings are magnetic.

(12) Set 1"IDx36" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
22" R.Pine N18E 18.55' mrkd "S1/16 BT"
6" Maple N72W 23.0' do
14" R.Pine S05E 18.7' do
7" W.Pine S84E 25.95' do
Set sq'd pine post adjacent.
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 12/06/2012

For the Michigan Department of Natural Resources, Forest Resources Division

