

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 20 T 43N R 16W	D8
	S 7 T 43N R 16W	6
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 6 06/06/2011 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(D8) Center of Section 20. Not previously monumented.

(6-Sec. 7) Northeast 1/16 corner, Section 7. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(D8) Established the position for the corner at the intersection of straight lines connecting
opposite 1/4 corners. Note: The monuments for Government corners C8, E8, and D7, placed in 2007 for
Schoolcraft County Remonumentation, were discovered to have been placed in erroneous positions. The
position for the 1/16 corner herein described was calculated using the proper positions for these
corners, based upon the method of reestablishment described in the certificates of record, L5 P453-4
and L5 P384. Schoolcraft County Remonumentation has expressed their intention to correct the
positions of the monuments for C8, E8, and D7.

(6-Sec. 7) Established the position for the corner at the intersection of straight lines connecting
opposite 1/16 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(D8) Set 1"IDx36" I.pipe with 4" alum. MNDR cap.
Set measuring nail with MDNR tag in the side of:
22" W.Pine N82W 17.75' mrkd "CS BT"
24" W.Pine S63W 33.2' do
10" W.Pine S61E 22.0' do
15" Cedar N43E 38.1' do
Set sq'd cedar post adjacent.
Bearings are magnetic.

(6) Set 1"IDx36" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
9" J.Pine N80E 24.9' mrkd "NE1/16 BT"
9" J.Pine S27E 32.0' do
7" J.Pine S32W 41.4' do
10" Cherry N14W 37.4' do
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 02/27/2012

For the Michigan Department of Natural Resources, Forest Resources Division



47505

47508