

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

| | | |
|---------------------------------------|-------------|---------------|
| Schoolcraft (County) | Located In: | Corner Code # |
| 1. Public Land Survey | T43N R 16W | K1 |
| | T R | |
| | T R | |
| 2. Property Controlling in Section | S T R | |
| | S T R | |
| 3. Miscellaneous Property in Sec. | S T R | |
| | S T R | |
| 4. Lot No. , Recorded Plat | | |
| 5. Private Claims | | |

Register of Deeds Stamp & File
Number

I, Stephan J. Szyszkoski, in a field survey on Oct. 24, 2007 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
(K1) Corner common to Sections 1-2 T43N-R16W and Sections 35-36 T44N-R16W. 1841 - Established by Wm.A.Burt Deputy Surveyor on the Township line midway between Section corner 80.00 chains west and Township corner 80.00 chains east. Set post. BTs: Aspen 8 N47E 39 links, Tamarack 6 N16W 43 links. 1969 - Reestablished by Frank J. Bray RLS on line and at the proportioned distance between town corner to east and section corner one mile west. Set 1" iron pipe with 4" aluminum cap. NBTs: 10" Balsam S89W 24.5 links, 5" Tamarack S73E 21.5 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
(K1) Recovered the 1969 monument in good condition and at record bearing and distance from the remains of the 1969 NBTs, now both dead and down. Verified the position of the corner with respect to Section corner 5277.18' west and Township corner 5275.82' east and found it to be in substantial accord with the 1969 record. Accepted the monument as a careful and faithful reestablishment of the position of the original corner. Found iron pipe monument presumed to have been either set at or left near the site of the corner by Carl Christensen N41W 49.8' distant, laying horizontal, out of position and disturbed, which I did not accept as marking the position for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
(K1) Found 1"ID I.pipe with 4" alum. State of Michigan cap. Set measuring nail with MDNR tag in the side of:
7" twin Maple S07W 17.37' mrkd "S2 NBT"
8" Maple S25E 17.12' "S1 NBT"
7" Spruce N01E 17.1' "S36 NBT"
9" W.Birch N74W 19.55' "S35 NBT"
Set a carsonite post 1.0' north.
Bearings are magnetic.



Signed by Stephan J. Szyszkoski Date 11/1/07

Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Office of Land and Facilities

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS