

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____ T. <u>44</u> N. <u>13</u> E. <u>W.</u>		G-11, E-11
2. PROPERTY CONTROLLING IN SECTION_____ T. _____ N. _____ S. _____ R. _____ E. _____ W. _____		
3. MISCELLANEOUS PROPERTY IN SECTION_____ T. _____ N. _____ S. _____ R. _____ E. _____ W. _____		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, David B. Babbitt, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 8-4 & 12-2, 1982, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

- G-11 S.E. Sec. Cor. of Sec. 28. O.B.T.'S. Wood Post, Cedar 18", N47°E, 6 lks. & Cedar 7", S50°W, 17 lks. M.S.H.D. Record: 1" iron pipe. 5" Spruce, N67°E, 36.83' & 15" Birch, N48°W, 44.64' & 5" Spruce, N80°W, 35.38'.
- B-11 North 1/4 cor. of Sec. 31. O.B.T.'S. Wood Post, Cedar 10", N88°E, 17 lks. & Cedar 12", S6°W, 8 lks.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- G-11 Set by re-tracing M.S.H.D. survey for M-77 (Proj. #75-11). Pipe and N.B.T.S. destroyed by road construction.
- B-11 Set from the remains of a Cedar blow down for the N.E. O.B.T. There is, also, the remains of another Cedar in the approx. position of the S.W. O.B.T. but so badly rotted that it is impossible to tell where it stood. The N.E. Cedar shows signs of having been scarred and partially healed over no actual blaze face or scribe marks are visible at this time. This cor. falls very near a proportionate position East and West for 2 1/2 miles East and 1/2 mile West to a U.S.E.S. Seney Refuge Monument.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- G-11 D.N.R. Monument. New Bearings: 7" Spruce, N70°W, 76.7' & 7" Cedar, S79°W, 108.08' & 10" Cedar, N79°W, 87.5' & Center Line M-77, East, 47.25
- B-11 D.N.R. Monument. New Bearings: 12" Hemlock, N64°W, 53.1' & 10" Cedar, N74°W, 80.6' & 10" Cedar, S65°E, 43.8' & 6" Maple, S9°W, 35.9'.

SIGNED BY David B. BabbittDATE 1-24-83SURVEYOR'S MICHIGAN REGISTRATION NO. 21558

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____

DATE _____

CHIEF OF SURVEY PARTY