

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft (County)	Located In:	Corner Code #
1. Public Land Survey	T 45N R 13W	I11
	T 45N R 13W	M11
	T	
2. Property Controlling in Section	S T	R
	S T	R
	S T	R
3. Miscellaneous Property in Sec.	S T	R
	S T	R
4. Lot No. _____, Recorded Plat _____		
5. Private Claims		

02/05/2008

02/05/2008

I, Stephan J. Szyszkoski, in a field survey on _____ do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(I11) Corner common to Sections 26-27-34-35. 1975 - Recovered and recorded by Thomas P. O'Brien RLS:
Found 8" squared post in fence line east and west and blazed line north. 10" twin Elm N10W 24.5', 6"
Maple S15E 15.4', 8" Maple S35W 41.9'. Recorded in L.1, P.124, Schoolcraft Co. Records.

(M11) Corner common to Sections 25-36 T45N-R13W and Sections 30-31 T45N-R12W. 1999 - Approved by
Luce Co. Remonumentation Program, Rec. in L.3, P.888, Luce Co. Records. Found 1" pipe with 4"
aluminum D.N.R. cap as recorded by Buckler in 1972. Accepted corner position as found. Red Maple
14" N06E 37.08', Red Maple 16" N40E 39.32', Spruce 9" S76E 24.92', Balsam 8" N35W 34.32', Red Maple
14" N12W 40.64'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(I11) The 8" squared post was not recovered. Found a 1/2" dia. rebar in a post hole at record
bearing and distance from the 1975 NBTs: the twin Elm is a stump, the 8" Maple SW is dead and down,
the 6" Maple SE is in good condition and with overgrown measuring nail scar but its bearing is S55E
from the corner, not S15E as stated in the record. Accepted the rebar as marking the 1975 position
and drove a new monument over the top of it. This corner is being recorded to update the monument
and accessories. Placed a new measuring nail with tag in the 1975 NBT Maple S55E.

(M11) Found the MDNR monument of record, in good condition, and at record bearing and distance from
the 1999 NBTs. The Red Maples NE are in good condition. The Spruce SE is a stump, the Balsam NW is
dead and down, the Red Maple NW is a stump. This corner is being recorded to update the accessories.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(I11) Found 1/2" rebar. Drove 1" IDx36" I.pipe
with plastic cap MICH DNR LS33986 over it.
Set measuring nail with MDNR tag in the side of:
8" Maple S55E 15.4' mrkd "S35 NBT" 1975 NBT
5" twin Maple N26E 4.85' "S26 NBT"
14" Birch N48W 23.5' "S27 NBT"
7" Maple S32W 18.05' "S34 NBT"
Bearings are magnetic.

(M11) Found 1" ID I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
7" Birch S08E 24.6' mrkd "S31 NBT"
7" Maple N41W 39.4' "S25 NBT"
The 1999 NBTs were found as follows:
Red Maple 14" N16E 37.08' mrkd "S30"
Red Maple 16" N51E 39.4' do
Bearings are magnetic.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7			8		9		10		11		12	
5													
6	18			17		16		15		14		13	
7													
8	19			20		21		22		23		24	
9													
10	30			29		28		27		26		25	
11													
12	31			32		33		34		35		36	
13													

Signed by

Stephan J. Szyszkoski

Surveyor's Michigan License No.

33986

Date

03/24/2008

For the Michigan Department of Natural Resources, Office of Land and Facilities

