LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

		/1	1				
Schoolcraft	Located In:	Corner Code #					
(County)	78						
1. Public Land Survey	TR						
2. Property Controlling in Section	S 33 T 46N R 13W S T R	F12					
3. Miscellaneous Property in Sec.	S T R S T R						
4. Lot No. , Rec	corded Plat		Register of I	Deeds Stam	р&File I	Number	Chit. M
			2 6 5	i li			20.
i, Stephan J. Szyszkoski , in that under requirements of P.A.	-	do hereby state or points mentioned in lines 1 and 2	3 - 1 - 0		_10_	-11-	
above were in conformance with r	regulations and rules therefore as req	uired in the current manual of survey	_ѵ ⋾├ ┈╎┈├ ╌┼	+	+	_ _	
a Court of Law and /or that the co	orner points mentioned in lines 3, 4 a	Land Management or by a decree of and 5 above were in conformance with	7	-16-	-15	14	13
the rules of the Michigan Board re-established, monumented, recove	J of Land Surveyors or by a Decre ered, found as expressed below:	ee of a Court of Law; established,	9 19 20		_22_	_23_	24
	ers, all in the same town and ${\sf ran}_{i}$	ge, may be recorded	10 30 29	28	-27-	-26-	25
on this certificate,		19	12 31 32	-	-34-	35	-36-

(F12) Center of Section 33. Not established in the original survey. 1991 - Established by Thomas P. O'Brien P.S. 21274 at the intersection of the N,S and E,W 1/4 lines. Set 1/2" Iron bar. 10" J.Pine S66W 103.0', 26" R.Pine N51W 93.9'. See Liber 2 of LCR, Page 324. 1999 - Certificate of Survey by Joseph C. Kapelczak PS 24598 dated Aug. 4, 1999 (Job no. M-6448-29 in NE1/4 Sec. 33): Found 1/2" rebar with cap #21274. Witnesses Set/Checked: [nail and JCK tag in] N78E 88.20' 8" Maple, S20W 68.00' 6" W.Pine, S66W 103.03' Jack Pine, N51W 93.92' 32" R.Pine. Mr. Kapelczak accepted the 1991 monument and used it to control title boundaries in the NE1/4 of Sec. 33.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A. Description of original monument and accessories and/or subsequent restoration:

(F12) The 1991 monument was not recovered and appears to have been removed by earthwork. Reestablished the 1991 position at record bearing and distance from the Jack Pine and Red Pine witnesses of record. Both were found in good condition with measuring nails and JCK identification tags. The remaining BTs were not recovered. Distances north and east to adjacent quarter corners check well with the dimensions given on the 1999 survey and confirm that the reestablished corner perpetuates both the 1991 and 1999 positions. I note that the position for this corner is not at the intersection of 1/4 lines as stated in the 1991 record. From the corner, the intersection of 1/4 lines is N75 deg. 48'44"W 36.34' (MCS83 grid bearing). As the monument has been accepted and used by others to control and monument title lines within this section, I accepted it as marking the position for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F12) Set 1" ID I.pipe with plastic MDNR cap.
12" J.Pine S70W 103.0' blazed with JCK nail/tag
30" R.Pine N47W 93.9' do
face of metal fnc.post (13th from SW cor of fnc)
S79W 5.6'
face of metal fnc.post (14th from SW cor of fnc)
S58E 2.65'
Bearings are magnetic.



Signed by

Surveyor's Michigan License No.

Date

01/04/2012

For the Michigan Department of Natural Resources, Forest Management Division

33986