## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	,	ng reduirement	OI ACI 74, WIII	лі. Г. <b>д.</b> 39. 	, 0						
Schoolcraft	Located In:	Corner Code	e#								
(County)											
1. Public Land Survey	T_46N R T_46N R T R	13W AB									
Property Controlling     in Section     Miscellaneous	S TR S TR S TR										
Property in Sec.	S TR				R	egiste	r of De	eds St	amp &	File N	umber
4. Lot No, Record 5. Private Claims				_	, <b>A</b>	ВС	D E	FG	: н	I J	K L
J. Filvate Claims	A8			-	1						ŢŢ
	85				3	Ϊ́Ι					T i
Stephan J. Szyszkoski	in a field survey on		do bereby stat	te that under					10		
requirements of P.A. 74, Michigan	P.A. of 1970, the corr	ner points mentioned in	n lines 1 and 2 at	oove were in	4	Ĺ	_ i _			11-	12
conformance with regulations and ru United States Department of the Int					5	T					
that the corner points mentioned in	n lines 3, 4 and 5 above	were in conformance	with the rules of t	he Michigan	7	18-		16	15	14-	13 
Board of Land Surveyors or by a recovered, found as expressed belo		of Law; established,	r <del>e es</del> tablished, п	onumented,			30				
•					8	19-				23- 	-1-24
NOTE: Not more than 2 come on this certificate.	rs, all in the same tov	vn and range, may b	e recorded		9 —	1					
Off this certificate,					10	1	29  	28	2 /	2 <del>6</del>	25
					11			33	34	Ţ	
					12	31		33	34	—35_ 	36
ridway and on line between sec links.		1 110/1 pape wash	- Gramina C	up. 10 0.	1110			inko, o	0. 12	110 JE	,, J,,
B. Description of corner evide			_	-				., .	45 05		
(85) Recovered the 1962 monume that Mr. Buckler reestablished AS and C5, and not midway betwo AS (MS T46N-R14W) upon which the R494.48° West and C5 2627.19°   It for a witness as described   (A8) Recovered the 1962 monume	and monumented the een them. However, he position of this East, being proport below. nt in good condition	e position for thi, the 1962 positio s corner depends, tionate to the ori on and at record b	s corner by prin for this cor I reestablishinginal record.	oportionate ner is not a ed 85 on a l Broke the a tance from t	measur iccepte ine of luminu	ement d due mean m cap	to the to my true to from to	e origin reestal pearing the 1962	nal rec blishme betwee 2 monum n good	ord be nt of n A5 ent ar condit	etween corner nd left
The 1962 position for this corporate the second of the second and on line be to the second and on line be to the second of the s	been established by	v Mr. Buckler. I	reestablished	this corner rom the corn	by sin er thu	igle p is est	roporti ablishe	ionate i ed, the	measure 1962 m	ment t onumer	at, now
"C." Description of monument to	it comerand access	sories established to	perpetuate loc	ating the pos	ition o	f the c	ougar.	erenen Hara	STATE OF THE PARTY	١.	
	<del>-</del> -		• •	alum.		4		*******	- A/A	<b>4</b>	
MDNR cap. Blazed, scribed, an		DNR cap. Blazed,		et		\$ 14	ST	EPHAN	7. ل ا		
measuring nails in : 6" Spruce N85M 20.55' "		easuring nails in: 2 J.Pine S75W 60.		" #		# #	SZ	EPHANYSZKO LAND IRVEYO NO. 33986	ski 1	计算	
10" W.Birch N42E 21.1'	•	" J.Pine S51E 8.95		<b></b>		第二	SI	UVAV9	ן מנ	4	
B" W.Birch N18E 37.1'	do 10	0" J.Pine N35E 29.	65' do			3	N.	No.	^^ <i>J</i> .		
10" W.Birch S57E 48.9'		" J.Pine N62W 29.6				2	, Adding	33986	TERRI LA		
l" iron pipe N89W 47.63′		earings are magnet		are to		•	1.0 (	AND S	0 8 V 15	ŭ.,	
Bearings are magnetic. Distan NBTs are to nail with tag.//		ail with tag. ∗d ith new,markings.	enotes the 196	Z MBI			- 80	A STANTES	Share.		
Signed by	// // //	shoot	!	Date	1	17	104				
Surveyor's Michigan License No	. T	33986	<u></u>		<u> </u>	1-1					
.,											