

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft (County)	Located In:	Corner Code #
1. Public Land Survey	T 46N R 16W	D3
	T 46N R 16W	E5
2. Property Controlling in Section	T	
	S	
	S	
3. Miscellaneous Property in Sec.	T	
	S	
	S	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 06/19/13 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(D3) Quarter corner common to Sections 5 and 8. 1963 - Billy D. Buckler RLS reestablished the position for the corner midway and on line between two Section corners. Set 1"ID I.pipe with 4" aluminum cap. 9" Soft Maple S16°W 34.5 links, 8" Soft Maple N45°W 35.5 links. Squared and scribed 5" Aspen at corner.

(E5) Corner common to Sections 8-9-16-17. 1963 - Billy D. Buckler RLS reestablished the corner position by double proportionate measurement to the original record. Set 1"ID I.pipe with 4" aluminum cap. 8" Soft Maple S47°E 63.5 links, 7" Soft Maple S36°W 94.5 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(D3) Found the 1963 monument in good condition and at record bearing and distance from the remaining 1962 witness Soft Maple N45°W 35.5 links, in good condition with overgrown blaze. The other 1962 accessory was not recovered. Accepted the monument as a careful and faithful reestablishment of the position of the original corner.

(E5) Found the 1963 monument in good condition and at record bearing and distance from the Soft Maple NBT S36°W 94.5 links, in good condition. The second NBT was also recovered in good condition but it is located 44' (66.7 links) from the monument, not 63.5 links as stated in the record. Accepted the monument as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(D3) Found 1"ID I.pipe with 4" alum. MI Dept. of Conservation cap. Set measuring nail with MDNR tag in the side of:
12" Maple N37°W 23.7' mrkd "1/4S" 1963 NBT
4" Cherry N86°W 5.05' mrkd "1/4S NBT"
4" Cherry N76°E 41.6' do
8" W.Pine S36°W 24.65' do
E= 8051144.073 N= 180393.996

(E5) Found 1"ID I.pipe with 4" alum. MI Dept. of Conservation cap. Set measuring nail with MDNR tag in the side of:
22" Maple S39°E 44.45' mrkd "S16" 1963 NBT
16" Maple S43°W 62.35' "S17" do
16" Maple N25°W 51.0' mrkd "S8 NBT"
8" Cherry N62°E 49.65' "S7 NBT"
E= 8051961.307 N= 178782.550

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).

Coord. Ref.=NGS PID RK0046: N= 173923.068 m. E= 8052746.340 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 10/10/2013

For the Michigan Department of Natural Resources, Forest Resources Division

